



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI ACTIVE
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 60 mph	12.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F





MOT history

MOT expiry date	2024-06-23
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	10
Total items failed	18

MOT #13 2023-06-21 15:24

MOT test number 653448293776

Result ✓ Passed

Next expiry date 2024-06-23

Advice Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Front Steering column deformed but serviceable (2.1.3 (c) (i))

Advice Under vehicle suspension/braking components slightly corroded

MOT #12 2023-06-19 17:19

MOT test number 825474329217

Result ✗ Failed

Advice Under vehicle suspension/braking components slightly corroded

Advice Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Front Steering column deformed but serviceable (2.1.3 (c) (i))

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))



MOT #11	2022-06-24 10:17
MOT test number	991154960510
Result	✓ Passed
Advice	Parking Brake High

MOT #10	2022-06-18 13:39
MOT test number	524316110203
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Registration plate inscription illegible FRONT & REAR (0.1 (b))

MOT #9	2022-05-06 12:21
MOT test number	614176402638
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #8	2021-02-11 17:13
MOT test number	621472976253
Result	✓ Passed

**MOT #7** 2020-08-24 13:58**MOT test number** 383292058008**Result** ✓ Passed**MOT #6** 2020-08-24 13:58**MOT test number** 871148603606**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2019-09-28 09:11**MOT test number** 937485988283**Result** ✓ Passed**MOT #4** 2018-10-04 16:18**MOT test number** 172614582004**Result** ✓ Passed**MOT #3** 2018-10-02 14:13**MOT test number** 309419570411**Result** ✗ Failed

- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))



MOT #2	2017-09-15 08:55
MOT test number	463475192090
Result	✓ Passed

MOT #1	2016-09-24 10:44
MOT test number	359286184257
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-10-06
Last registration	2023-06-21
Complete history	See info



Registration #1	2013-10-06	13 mi
Registration #2	2016-09-24	21.240 mi
Registration #3	2017-09-15	27.926 mi
Registration #4	2018-10-02	37.312 mi
Registration #5	2018-10-04	37.312 mi
Registration #6	2019-09-28	45.517 mi
Registration #7	2020-08-24	51.646 mi
Registration #8	2020-09-29	51.777 mi
Registration #9	2020-09-29	51.777 mi
Registration #10	2020-09-29	51.777 mi
Registration #11	2020-09-29	51.777 mi
Registration #12	2020-09-29	51.777 mi
Registration #13	2020-09-29	51.777 mi
Registration #14	2020-09-29	51.777 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1440 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBDZ537155