





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	5008 HDI SPORT
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history


## Entry 1

Date 2021-09-26

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT expiry date	2023-11-06
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	27
Total items failed	1

MOT #13		2022-11-07 15:32
MOT test	number	289930823707
Result		<b>✓</b> Passed
Next expi	ry date	2023-11-06
Advice	Nearside Front wheel arch cover insecure	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement		
front and r	rear bushes (5.3.4 (a) (i))	
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously v	veakened (1.1.14 (a) (ii))

MOT #12		2022 11 02 12 15
MOT #12		2022-11-03 13:15
MOT test	number	383721363369
Result		<b>×</b> Failed
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))
<b>MAJOR</b> ingress of	Nearside Front Drive shaft joint constant velocity boot split or insecure, no dirt $(6.1.7 (g) (ii))$	o longer prevents the
<b>Advice</b> front and	Offside Front Lower Suspension arm pin or bush worn but not resulting in rear bushes (5.3.4 (a) (i))	excessive movement
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice	Nearside Front wheel arch cover insecure	
MAJOR	Rear Exhaust system insecure mounting (6.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #11** 2021-10-18 14:31

**MOT test number** 919312988660

MOT #10 2020-10-29 08:52

**MOT test number** 846479071367

**Result** 
✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2020-10-27 09:34

**MOT test number** 328661865070

Result X Failed

**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #8 2019-05-03 13:15

**MOT test number** 513557426659

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

MOT test number

2018-05-04 09:44

247794844025

Result

Advice Offside Front Tyre worn close to the legal limit very worn on inner edge (4.1.E.1)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #5 2017-05-04 13:23

MOT test number 803655419979

Result ✓ Passed

MOT #4 2016-02-01 15:07
MOT test number 376947216256
Result ✓ Passed

MOT #3

MOT test number

900284295034

Result

X Failed

Fail Nearside Front coil spring broken (2.4.C.1a)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2	2015-01-23 10:27
MOT test number	289753325035
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2014-01-20 17:23
MOT test number	267320624008
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



Tax expired: 12 October 2023

# X MOT

**Expired:** 6 November 2023

Tax status	Expired at 12 October 2023
Days left	200 days too late
MOT expiry date	6 November 2023
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

$\sim$				
-( )v	vner	hi	ะะก	ı۲
$\sim$ v	V I C I		,,,,	

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
*********	
************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIN
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-01-26
Last registration	2022-11-07
Complete history	See info



Registration #1	2011-01-26	16 mi
Registration #2	2014-01-20	30.374 mi
Registration #3	2015-01-23	36.951 mi
Registration #4	2016-01-30	48.274 mi
Registration #5	2016-02-01	48.306 mi
Registration #6	2017-05-04	65.177 mi
Registration #7	2018-05-04	80.800 mi
Registration #8	2019-05-03	96.241 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



# Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1577 kg
Max. allowed weight	2250 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1:

Number of axles 2

**Engine number** JBER3024943