





General information

Make	PEUGEOT
Model	207 HDI S
Colour	Silver
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	14.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg



MOT history

MOT #12	2020-10-23 10:14
MOT test number	233823617667
Result	✓ Passed
Next expiry date	2021-11-20
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11	2020-10-22 07:56
MOT test number	495226223579
Result	🗙 Failed
Fail Brake pedal anti-slip provision missing (1.1.2 (c))	
FailOffside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #10		2019-11-20 09:56
MOT test	number	143619789057
Result		✓ Passed
Advice	Offside Rear exhaust bracket broken	
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Central Front radiator leak	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2018-11-07 16:04
MOT test	number 983390871806
Result	✓ Passed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	





МОТ #8	2017-11-17 17:16
MOT test number	847360841191
Result	✓ Passed
Advice Nearside Front uneven tyre wear	
MOT #7	2017-11-16 14:12
MOT test number	962763883880
Result	🗙 Failed
Fail Offside Front constant velocity joint gaiter damaged to the extent that it no lo ingress of dirt etc (2.5.C.1a)	nger prevents the
Advice Central Front Exhaust heat shield insecure PARTIALLY	
Advice Central Front Exhaust bracket rusted off	
Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no ingress of dirt etc (2.5.C.1a)	longer prevents the
Advice Nearside Front uneven tyre wear	

МОТ #6	2016-11-21 15:41
MOT test number	341268605377
Result	✓ Passed

MOT #5	2015-11-19 14:39
MOT test number	705666483889
Result	✓ Passed
Advice Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)	





MOT #4		2014-09-29 15:27
MOT test	number	316932374217
Result		✓ Passed
Advice	Nearside Outer Front Tie bar/rod has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2013-09-20 12:13
MOT test number	266183763293
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	

MOT #2	2012-09-11 09:52
MOT test number	757165252206
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	

MOT #1		2012-09-11 09:52
MOT test number		339395552240
Result		🗙 Failed
Pass with rectification	Front registration plate delaminated (6.3.1d)	
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)		





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-09-28
Last registration	2020-10-23
Complete history	See info



Registration #1	2009-09-28	20 mi
Registration #2	2012-09-11	30.595 mi
Registration #3	2013-09-20	39.801 mi
Registration #4	2014-09-29	44.372 mi
Registration #5	2015-11-19	49.247 mi
Registration #6	2016-11-21	53.775 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		
		10.317 mil
Registration #11		11.777 es





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1261 kg
Max. allowed weight	1660 kg
Additional information	
Fuel tank capacity	50
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10

Number of axles	2
Engine number	FDAX2402683