






report date: 2024-03-29

General information

Make	FORD
Model	KUGA LX TDCI
Colour	Black
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



Internet history


Entry 1


Date 2021-05-25


Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2022-01-26
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	25
Total items failed	1

MOT #12		2021-01-27 15:12
MOT test	number	351470186175
Result		✓ Passed
Next expi	ry date	2022-01-26
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge replace soon (5.2.3	(e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge replace soon (5.2.3 (e))
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly wor	rn (5.1.2 (b) (i))

MOT #11		2021-01-27 13:49
MOT test	number	957630245917
Result		X Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly wo	orn (5.1.2 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge replace soon (5.2.3	(e))
Fail Re	egistration plate lamp inoperative in the case of a single lamp or all lamps (4.7	7.1 (b) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge replace soon (5.2.	3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #10

MOT test number

781935961405

Result

Advice Nearside Rear Nail in tyre

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2018-11-02 11:00 **MOT** test number 692475653724 Result ✓ Passed **MOT** #8 2017-11-06 10:16 **MOT test number** 542363306222 Result Passed **Advice** Nearside Front tyre tread cut but not through to cords at time of test **Advice** Nearside Front Nail in tyre

MOT #7

MOT test number

645915416454

Result

Advice Rear Brake lining(s) wearing thin (3.5.1g)

Advice Front Brake lining(s) wearing thin (3.5.1g)

 MOT #6
 2015-11-10 10:55

 MOT test number
 368955480200

 Result
 ✓ Passed

 MOT #5
 2015-05-19 14:35

 MOT test number
 739669835116

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



MOT #4

MOT test number

Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Notice Nail in offside rear tyre

Notice Engine covers fitted obscuring some components in the engine bay

 MOT #1
 2011-05-06 08:59

 MOT test number
 156436521100

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



X MOT

Tax expired:
30 June 2021

Expired: 26 January 2022

Tax status	Expired at 30 June 2021
Days left	1034 days too late
MOT expiry date	26 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
HARMAN CONTRACTOR CONT	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-05-23
Last registration	2021-01-27
Complete history	See info



Registration #1	2008-05-23	17 mi
Registration #2	2011-05-06	28.956 mi
Registration #3	2012-05-16	33.169 mi
Registration #4	2013-05-17	40.799 mi
Registration #5	2014-05-19	47.221 mi
Registration #6	2015-05-19	52.649 mi
Registration #7	2015-11-10	54.773 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2
Engine number 8R41969