



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI SW S
Colour	Grey
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-29
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	22
Total items failed	11

MOT #18	2023-09-30 13:48
MOT test number	462938321990
Result	✓ Passed
Next expiry date	2024-09-29

MOT #17	2023-09-29 13:07
MOT test number	950987997540
Result	✗ Failed
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2022-09-17 13:14
MOT test number	591954286414
Result	✓ Passed

MOT #15	2021-12-16 14:50
MOT test number	781597019614
Result	✓ Passed

**MOT #14** 2021-12-16 09:37**MOT test number** 945303241490**Result** ✗ Failed**Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #13** 2020-12-24 15:08**MOT test number** 670004130625**Result** ✓ Passed**Advice** Vehicle under body has been under sealed**MOT #12** 2020-02-20 10:26**MOT test number** 356694115693**Result** ✓ Passed**Advice** Heatshields loose**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**Advice** Rear Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security rear inner sills (6.2.2 (d) (i))**MOT #11** 2020-02-19 12:28**MOT test number** 281753032140**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Heatshields loose**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security rear inner sills (6.2.2 (d) (i))



**MOT #10**

2019-03-14 09:15

**MOT test number**

501406720151

**Result**

✓ Passed

- Advice** Nearside Front tyre worn on outer edge
- Advice** Offside Rear tyre has age related cracks
- Advice** Nearside Rear tyre has age related cracks
- Advice** Offside Front tyre worn on outer edge

**MOT #9**

2018-03-10 15:21

**MOT test number**

265060062669

**Result**

✓ Passed

- Advice** Coil spring corroded all coil springs (2.4.C.1b)
- Advice** Brake hose has slight corrosion to ferrules all hoses (3.6.B.4e)
- Advice** Rear wheels binding slightly
- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #8**

2018-03-10 11:57

**MOT test number**

302696230351

**Result**

✗ Failed

- Fail** Offside Front Suspension arm inappropriately repaired ball joint incorrectly positioned (2.4.A.2)
- Advice** Rear wheels binding slightly
- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Coil spring corroded all coil springs (2.4.C.1b)
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Brake hose has slight corrosion to ferrules all hoses (3.6.B.4e)

**MOT #7** 2017-03-20 08:42**MOT test number** 389611599144**Result** ✓ Passed**MOT #6** 2016-06-29 11:24**MOT test number** 557405452504**Result** ✓ Passed**MOT #5** 2015-06-11 14:21**MOT test number** 686522465145**Result** ✓ Passed**MOT #4** 2015-06-11 14:21**MOT test number** 615832865158**Result** ✗ Failed

**Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Pass with rectification** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #3** 2014-06-19 14:25**MOT test number** 655180974195**Result** ✓ Passed**MOT #2** 2013-06-17 15:56**MOT test number** 587008863124**Result** ✓ Passed



MOT #1	2012-06-19 14:22
MOT test number	936211572185
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	29 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>ML09YWR</b>
Plate since	2019-03-29
Current registration	<b>ML09YWR</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-30
Last registration	2023-09-30
Complete history	<a href="#">See info</a>



Registration #1	2009-06-30	8 mi
Registration #2	2012-06-19	19.597 mi
Registration #3	2013-06-17	26.400 mi
Registration #4	2014-06-19	33.504 mi
Registration #5	2015-06-11	40.077 mi
Registration #6	2016-06-29	49.992 mi
Registration #7	2017-03-20	54.088 mi
Registration #8	2018-03-10	61.234 mi
Registration #9	2018-03-10	61.234 mi
Registration #10	2019-03-14	67.633 mi
Registration #11	2019-03-20	75.277 mi
Registration #12	2019-03-20	75.277 mi
Registration #13	2019-03-20	75.277 mi
Registration #14	2019-03-20	75.277 mi
Registration #15	2019-03-20	75.277 mi
Registration #16	2019-03-20	75.277 mi
Registration #17	2019-03-20	75.277 mi
Registration #18	2019-03-20	75.277 mi
Registration #19	2019-03-20	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4149 mm
Wheel base	2540 mm
Kerb weight	1332 kg
Max. allowed weight	1741 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JBBX3039830