





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Yellow
Year of manufacture	2006
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/14



MOT history

MOT expiry date	2024-09-02
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	42
Total items failed	10

MOT #18	2023-08-25 14:16
MOT test number	374898682180
Result	✓ Passed
Next expiry date	2024-09-02
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #17		2023-08-25 14:16
MOT test number		782742101356
Result		X Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear S	ervice brake binding but not excessively (1.2.1 (f))	

MOT #16	2022-08-24 13:34
MOT test number	675666189228
Result	✓ Passed

CarCheck.co.uk page 2/14



MOT #15 2021-09-03 07:07

MOT test number 196456509942

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Rear tyre getting out of shape slightly

MOT #14 2020-09-02 09:54

MOT test number 842684713070

Result ✓ Passed

MOT #13 2019-05-01 08:32

MOT test number 651425766127

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2018-04-21 09:21

MOT test number 691621196731

Result

Passed

Advice Front pads low.

MOT #11 2017-05-06 08:58

MOT test number 471480821410

CarCheck.co.uk page 3/14



MOT #10 2016-05-13 10:55

MOT test number 867983517725

Result \rightarrow Passed

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

MOT #9 2016-05-11 10:53

MOT test number 421828281163

Result X Failed

Fail Nearside Front Direction indicator not working (1.4.A.2c)

Fail Indicator tell tale inoperative (1.4.A.2a)

Advice Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (4.1.D.1b)

Fail Nearside Rear Direction indicator not working (1.4.A.2c)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (4.1.D.1b)

MOT #8 2015-05-13 15:12

MOT test number 275113535484

Result / Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

CarCheck.co.uk page 4/14



MOT #7 2015-05-13 12:50

MOT test number 339833735178

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Nearside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #6 2014-05-13 12:28

MOT test number 109893734169

Result \(\sqrt{Passed} \)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Both rear tyres slightly perished

Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #5 2013-05-09 16:59

MOT test number 219349923479

Result

Passed

Notice N/s rear footbrake effort slightly low

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system

requires adjustment or repair. (3.7.B.7)

Notice Slight beam distortion to o/s front headlamp

Notice Damage to windscreen outside swept area

CarCheck.co.uk page 5/14



MOT #4 2012-02-02 14:14

MOT test number 196613332084

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Exhaust hangers corroded

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice Front brake discs worn and pitted

MOT #3 2011-01-31 14:40

MOT test number 738501431042

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear tyres slightly perished

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Front discs worn and pitted

MOT #2 2010-02-02 15:21

MOT test number 402623530018

Result ✓ Passed

Advice Nearside Front brake disc slightly pitted (3.5.1h)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc slightly pitted (3.5.1h)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



LV06NKX

report date: 2024-03-28

MOT #1		2009-02-02 09:44
MOT test	number	853253739003
Result		✓ Passed
Advice	Nearside Front brake disc slightly pitted (3.5.1h)	
Advice	Offside Front brake disc slightly pitted (3.5.1h)	

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	2 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manus .	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIN
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-03-28
Last registration	2023-08-25
Complete history	See info



Registration #1	2006-03-28	26 mi
Registration #2	2009-02-02	6.779 mi
Registration #3	2010-02-02	15.996 mi
Registration #4	2011-01-31	23.009 mi
Registration #5	2012-02-02	30.130 mi
Registration #6	2013-05-09	36.942 mi
Registration #7	2014-05-13	41.728 mi
Registration #8	2015-05-13	47.669 mi
Registration #9	2015-05-13	47.670 mi
Registration #10	2016-05-11	53.788 mi
Registration #11		71.777 es
Registration #12		
		W
Registration #13		11.777 es
Registration #13 Registration #14		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #14		11.777 es 11.777 es 11.777 es
Registration #14 Registration #15		11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16		11,777 esi 11,777 esi 11,777 esi 11,777 esi 11,777 esi

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	5232018

CarCheck.co.uk page 14/14