



LF08NJE

report date: 2024-03-28

General information

Make	FORD
Model	GALAXY
Colour	Green
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.753 cc
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



## MOT history

MOT expiry date	2023-11-27
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	45
Total items failed	22

MOT #23 2022-11-28 15:16

MOT test number 907700512948

Result ✓ Passed

Next expiry date 2023-11-27

- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases Front flexi (6.1.2 (a))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn to 2mm (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases centre pipie (6.1.2 (a))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #22**

2022-11-22 12:39

**MOT test number**

115583169830

**Result****✗ Failed**

- Fail** Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Exhaust has a minor leak of exhaust gases centre pipie (6.1.2 (a))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))
- Fail** Horn not working (7.7 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn to 2mm (5.2.3 (e))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases Front flexi (6.1.2 (a))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn to 2mm (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #21** 2021-09-22 14:30**MOT test number** 393244439784**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #20** 2020-12-09 17:06**MOT test number** 469127409912**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #19** 2020-12-09 11:16**MOT test number** 658809442158**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #18** 2019-12-16 12:17**MOT test number** 476625035721**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2019-12-16 12:16**MOT test number** 423721583960**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2018-12-12 10:44**MOT test number** 489090094838**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15** 2017-12-19 17:43**MOT test number** 155318522640**Result** ✓ Passed

**MOT #14** 2017-12-19 17:43**MOT test number** 556996221065**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Headlamp aim too high (1.8)

**MOT #13** 2015-05-15 09:02**MOT test number** 217275235426**Result** ✓ Passed**MOT #12** 2015-05-15 09:02**MOT test number** 688845135163**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**MOT #11** 2014-04-16 12:54**MOT test number** 157236404178**Result** ✓ Passed

- Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)

**MOT #10** 2014-04-16 12:54**MOT test number** 205606704107**Result** ✗ Failed

- Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)
- Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #9** 2013-10-23 14:42**MOT test number** 986526793229**Result** ✓ Passed**MOT #8** 2013-10-23 14:42**MOT test number** 685626893289**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2013-04-24 11:39**MOT test number** 439424513115**Result** ✓ Passed**MOT #6** 2013-04-24 11:39**MOT test number** 236564113106**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-03-25 11:49**MOT test number** 906384083021**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Handbrake high**Advice** Front Brake pad(s) wearing thin (3.5.1g)



**MOT #4** 2013-03-21 16:42**MOT test number** 418940483038**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Notice** Handbrake high**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2012-02-17 12:41**MOT test number** 559418542078**Result** ✓ Passed**MOT #2** 2012-02-17 12:41**MOT test number** 225368242055**Result** ✗ Failed**Pass with rectification** Offside Rear Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**MOT #1** 2011-03-03 13:03**MOT test number** 119012761086**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-13
Last registration	2022-11-28
Complete history	<a href="#">See info</a>



Registration #1	2008-05-13	13 mi
Registration #2	2011-03-03	81.029 mi
Registration #3	2012-02-17	113.386 mi
Registration #4	2013-03-21	120.095 mi
Registration #5	2013-03-25	120.098 mi
Registration #6	2013-04-24	126.116 mi
Registration #7	2013-10-23	146.457 mi
Registration #8	2014-04-16	168.758 mi
Registration #9	2015-05-15	173.763 mi
Registration #10	2017-12-19	175.655 mi
Registration #11	2019-05-20	181.377 mi
Registration #12	2019-05-20	181.377 mi
Registration #13	2019-05-20	181.377 mi
Registration #14	2019-05-20	181.377 mi
Registration #15	2019-05-20	181.377 mi
Registration #16	2019-05-20	181.377 mi
Registration #17	2019-05-20	181.377 mi
Registration #18	2019-05-20	181.377 mi
Registration #19	2019-05-20	181.377 mi
Registration #20	2019-05-20	181.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	2
Engine number	NOT KNOWN