





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO L2H1 F3500 TIPPER
Colour	White
Year of manufacture	2018
Top speed	91 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.8 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2022-01-09

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2024-03-29
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #3		2024-03-19 17:59
MOT test	number	333004409875
Result		X Failed
MAJOR	Nearside Rear Outline marker lamp missing (4.2.1 (a) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR (a))	Outline marker lamp does not illuminate simultaneously with the position lam	nps Both side (4.2.2
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both side	(1.1.14 (a) (ii))
MAJOR	Front Fuel system component leaking Filter slight seepage (6.1.3 (b) (i))	
MAJOR (4.4.1 (b)	Nearside Side repeater lens defective such that the emitted light is adversely (ii))	affected Missing
Minor	Offside Rear Headlamp lens slightly defective cracked (4.1.1 (b) (i))	
MAJOR	Offside Rear Outline marker lamp missing (4.2.1 (a) (ii))	
MAJOR	Nearside Outline marker lamp missing Centre (4.2.1 (a) (ii))	
DANGE	ROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR (6.2.1 (a)	Nearside Body component damaged and likely to cause injury centre on pane	el door plastic edges
Advice	Nearside Body component slightly loose Mirror housing loose (6.2.1 (a) (i))	
Advice	Front Brake disc worn, but not excessively Both side (1.1.14 (a) (i))	
MAJOR	Nearside Side repeater incorrect colour (4.4.3 (a))	

CarCheck.co.uk page 3/10



MOT #2

MOT test number

916092016020

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #1
 2022-01-24 10:53

 MOT test number
 475445392935

 Result
 ✓ Passed

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category
Type

Damage 2

Category

Date

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



More info >

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-11-30
Last registration	2024-03-19
Complete history	See info



Registration #1	2018-11-30	12 mi
Registration #2		71.777 66
Registration #3	2022-01-24	60.791 mi
Registration #4		71.777 66
Registration #5		11,177 mi

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2370 mm
Length	5819 mm
Kerb weight	2306 kg
Max. allowed weight	3500 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	M9T -C132152 L0B

CarCheck.co.uk page 10/10