





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ST-LINE
Colour	Black
Year of manufacture	2018
Top speed	125 mph
0 - 100 km/h	9.9 seconds
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 138 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	98 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-08


Pictures 9

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-01
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #6		2023-04-25 10:23	
MOT test	number	260858869309	
Result		✓ Passed	
Next expi	ry date	2024-05-01	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2023-04-24 10:45 **MOT** test number 197118753534 Result × Failed **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #2
 2021-04-10 09:35

 MOT test number
 409598816747

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Pass with rectification (iii)

Pass with rectification Offside Windscreen wiper not working (3.4 (a))

CarCheck.co.uk page 5/12



MA18WLV report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-02
Last registration	2023-04-25
Complete history	See info



Registration #1	2018-05-02	7 mi
Registration #2	2021-04-10	20.218 mi
Registration #3	2021-04-10	20.218 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



MA18WLV report date: 2024-03-28

Car features

	 •	-	•	•	
S0225					Air conditioning
S0295					
S0482					
S0501					
S0566					

View the complete FORD factory list for this vehicle <u>here</u>.

The FORD factory car options list is only available in the premium report.

More info >

Safety ratings

S0567 S0569

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	64%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1941 mm
Height	1476 mm
Length	4040 mm
Wheel base	2493 mm
Kerb weight	1064 kg

Additional information

Fuel tank capacity	42 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	JS33927 page 12/12