





report date: 2024-03-28

General information

Make	BMW
Model	525 525D SE
Colour	Grey
Year of manufacture	2007
Top speed	143 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.497 сс
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	185 g/km
CO2 label	ı



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-02

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-27
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	20
Total items failed	5

MOT #19	2023-11-28 09:54
MOT test number	140481473396
Result	✓ Passed
Next expiry date	2024-11-27
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #18		2022-10-10 13:15
MOT test	number	597351411714
Result		✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nail in tyre 3 Tyres (both front nearside rear)	
Advice	Exhaust emits blue smoke during acceleration (8.2.1.2 (g))	

CarCheck.co.uk page 3/14



Fail

WL070FV

report date: 2024-03-28

MOT #17

MOT test number

943701328654

Result

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nail in tyre 3 Tyres (both front nearside rear)

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

 MOT #16
 2021-09-23 13:21

 MOT test number
 205159925163

Result ✓ Passed

MOT #15 2021-09-17 07:34

MOT test number 323231449890

Result X Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Exhaust particulate filter obviously defective (8.2.2.1 (a))

MOT #14 2020-09-17 14:55

MOT test number 881385530038

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Outer Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MO1 #13	2019-09-30 08:17
MOT test number	418965567025

Result ✓ Passed

MOT #12 2019-06-07 07:55

MOT test number 486702579668

Result ✓ Passed

MOT #11 2018-06-25 14:12

MOT test number 471083416930

Result
✓ Passed

MOT #10 2018-06-18 15:54

MOT test number 705065164165

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2017-02-22 12:19

MOT test number 849198132328

Result ✓ Passed

MOT #8 2017-02-21 10:41

MOT test number 339098370819

Result X Failed

Fail Parking brake lever ratchet mechanism is excessively worn (3.1.5)

MOT #7 2016-02-18 15:44

MOT test number 493078681419

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #6 2015-02-25 09:41

MOT test number 156106755000

MOT #5 2014-02-27 11:51

MOT test number 726658854085

Result Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2013-02-22 16:40

MOT test number 137383153420

Result \rightarrow Passed

MOT #3 2012-02-23 09:49

MOT test number 218054052001

MOT #2 2011-02-24 15:18

MOT test number 887115051024

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1

MOT test number

152557250466

Result

Notice All tyres cracking around tread surface

Notice Rear tyres on 2.5mm

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



funda scincos

WL070FV

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this BMW had different number plates. nber of plates

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-01
Last registration	2023-11-28
Complete history	See info



Registration #1	2007-03-01	10 mi
Registration #2	2010-02-26	14.300 mi
Registration #3	2011-02-24	20.781 mi
Registration #4	2012-02-23	23.696 mi
Registration #5	2013-02-22	26.976 mi
Registration #6	2014-02-27	29.390 mi
Registration #7	2015-02-25	32.241 mi
Registration #8	2016-02-18	35.932 mi
Registration #9	2017-02-21	41.398 mi
Registration #10	2017-02-22	41.398 mi
Registration #11	2018-06-18	42.499 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 esi

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1585 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number 23786467