





# General informationMakeVAUXHALLModelVIVARO L2H1 2900 CDTIColourWhiteYear of manufacture2017Gearbox6 speed Manual

# Engine & fuel consumption

Power	118 BHP	0 < 101 A
Max. torque	300 Nm at 1.750 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	1.598 cc	121 - 140 P
Cylinders	4	141 - 165 G
Fuel type	Diesel	166 - 185 H LABEL H
Consumption city	35.3 mpg	186 - 225 J
Consumption extra urban	47.1 mpg	225+ L
Consumption combined	42.2 mpg	
CO2 emission	174 g/km	
CO2 label	Н	



DY67MVF report date: 2024-03-28

Internet history		
Entry 2		
Date	2021-06-23	
Pictures	12	
Listing price	View report	
PARTEX, WELCOME source: cargurus.co.uk	HIGHLY RATED AA	Proud to be part of the Garage Guide Certified Garage
Date	2021-06-22	
Pictures	31	
Listing price	View report	
Approved Finance Partner		



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-12-04
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	5
Total items failed	4

МОТ #5	2023-12-05 15:30
<b>MOT test number</b> 363397520	
Result	🗸 Passed
Next expiry date	2024-12-04
Advice Nearside Front Inner Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	
Advice Anti-roll bar pin or bush worn but not resulting in excessive movement Both front anti roll bar d bushes (5.3.4 (a) (i))	
Advice Underside of vehicle heavily covered in clay	
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

МОТ #4	2022-11-25 08:12
MOT test number	308053708642
Result	✓ Passed

MOT #3	3	2022-11-22 16:05
MOT te	st number	315480590049
Result		🗙 Failed
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail	ail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	



<b>DY67</b>	Μ	V	F
report date	e: 202	24-0	3-28

MOT #2	2021-09-08 16:57
MOT test number	596984750308
Result	✓ Passed
MOT #1	2020-09-09 08:02
MOT test number	310893742971
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 September 2024 Tax status	4 December 2024 Valid until 1 September
Days left	126
MOT expiry date	4 December 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-08
Last registration	2023-12-05
Complete history	<u>See info</u>



Registration #1	2017-09-08	24 mi
Registration #2	2020-09-09	52.137 mi
Registration #3		11.777 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		10.300 est

More info  $\rightarrow$ 





# Safety ratings

NCAP rating		Junia Contra
Adult	52%	EURO
Children	91%	
Pedestrian	53%	-
Safety systems	57%	
Overall rating	61%	
Video	see crash video	

Dimensions & weight	
Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1900 kg
Max. allowed weight	2940 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	R9M MK - C058068LWZ