





General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Grey
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	М







Internet history

Entry 2	
Date	2022-01-09
Pictures	14
Listing price	View report



source: yesauto.com

Entry 1	
Date	2021-07-21
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-07
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	54
Total items failed	11

MOT #20	2023-01-07 09:24
MOT test number	736556944964
Result	✓ Passed
Next expiry date	2024-01-07
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #19 2022-01-08 17:46 MOT test number 241041127897 Result Image: Passed Advice Offside Rear Seat belt buckle slightly damaged casing (7.1.2 (d)) Advice Underbody and components undersealed Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

MOT #18	2020-12-18 17:35
MOT test nu	amber 581633522425
Result	✓ Passed
Advice	Underseal
Advice (8.2.2.2 (c))	Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users





MOT #17		2019-06-06 16:11
MOT test I	number	415054052352
Result		✓ Passed
Advice (8.2.2.2 (c)	Exhaust emits excessive smoke or vapour but not likely to obscure the vis)	ion of other road users
MOT #16		2019-06-06 11:44
MOT test ı	number	272976174511
Result		🗙 Failed
Advice (8.2.2.2 (c)	Exhaust emits excessive smoke or vapour but not likely to obscure the vis)	ion of other road users
MAJOR	Oil leaking excessively from engine (8.4.1 (a) (i))	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #15		2018-06-04 14:12
MOT test	number	668367028633
Result		✓ Passed
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting surfac	e (4.8.1 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Minor	Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))





MOT #14		2018-06-02 13:22
MOT test	number	244855280846
Result		🗙 Failed
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
MAJOR (5.2.3 (d)	Nearside Front Tyre has a cut in excess of the requirements deep enough (i))	to reach the ply or cords
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting	surface (4.8.1 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR (5.2.3 (d)	Offside Front Tyre has a cut in excess of the requirements deep enough to (i))	o reach the ply or cords
Minor	Offside Windscreen damaged but not adversely affecting driver's view (3.2	(a) (i))

MOT #13		2017-05-06 12:06
MOT test	number	383141074214
Result		✓ Passed
Advice	Front Outer Tyre worn close to the legal limit both side (4.1.E.1)	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Oil leak	
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone ',	A' (8.3.1a)

MOT #12		2016-01-22 14:42
MOT test	number	648701858144
Result		✓ Passed
Advice	EML WARNING LIGHT ON	
Advice	ENGINE OIL LEAK	
Advice	Offside Rear Rear reflector obscured but not more than 50% (1.5.1b)	





MOT #11	2016-01-21 12:57	
MOT test number	769165432533	
Result	🗙 Failed	
Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)		
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)		
Advice Offside Rear Rear reflector obscured but not more than 50% (1.5.1b)		
Advice ENGINE OIL LEAK		
Fail Offside Rear Seat belt damaged sufficient to obstruct correct operation of the belt 2nd row stalk outre casing damaged (5.2.2a)		
Fail Offside Front Headlamp not working on dipped beam (1.7.5a)		
Advice EML WARNING LIGHT ON		

MOT #10		2014-06-10 08:50
MOT test	number	228521964160
Result		✓ Passed
Notice	ENGINE LIGHT ON	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Oil leak	





МОТ #9	2014-06-05 14:53
MOT test number	286506354461
Result	🗙 Failed
Notice ENGINE LIGHT ON	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Oil leak	
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #8		2013-05-15 15:05
MOT test	number	669235433120
Result		✓ Passed
Notice	Oil leak	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Under-trays fitted obscuring some underside components	

MOT #7	2013-05-15 15:05
MOT test number	865305533196
Result	🗙 Failed
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice Oil leak	
Pass with rectification Front Headlamp aim too high (1.8)	
Notice Under-trays fitted obscuring some underside components	





MOT #6	2013-05-10 15:40
MOT test number	217670033436
Result	🗙 Failed
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach (4.1.D.1a)	the ply or cords
Notice EML ON	
Fail Offside Rear Seat belt damaged sufficient to obstruct correct operation of the belt	(5.2.2a)
Notice Under-trays fitted obscuring some underside components	
Advice Rear Parking brake: parking brake efficiency only just met. It would appear tha system requires adjustment or repair. (3.7.C.1b)	t the braking
Notice Front offside tyre cut in outer sidewall worn grove	
Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Notice Oil leak	
Notice Engine covers fitted obscuring some components in the engine bay	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #5	2012-05-30 18:12
MOT test number	577041252104
Result	✓ Passed

МОТ #4	2012-03-12 16:27
MOT test number	298492572062
Result	✓ Passed

МОТ #3		2012-03-12 16:27
MOT test number		508572672080
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)	





MOT #2	2011-03-09 16:32
MOT test number	165118961495
Result	✓ Passed
MOT #1	2010-03-10 10:54
MOT test number	770469260065
Result	✓ Passed



OV07OCE report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 16 November 2023	X MOT Expired: 7 January 2024
Tax status	Expired at 16 November 2023
Days left	164 days too late
MOT expiry date	7 January 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	Μ
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
	E Stand
Date	N. Sterring and a start of the
Category	ame
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Carrent registration	
Carrent registration Plate since	
Carrent registration Faits since Carrent registration	
Carrent registration Plate since Carrent registration Plate since	8775-25-27





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-11
Last registration	2023-01-07
Complete history	See info



Registration #1	2007-04-11	19 mi
Registration #2	2010-03-10	25.465 mi
Registration #3	2011-03-09	39.834 mi
Registration #4	2012-03-12	59.938 mi
Registration #5	2012-05-30	60.963 mi
Registration #6	2013-05-10	67.445 mi
Registration #7	2013-05-15	67.564 mi
Registration #8	2014-06-05	73.613 mi
Registration #9	2014-06-10	73.618 mi
Registration #10	2016-01-21	82.300 mi
Registration #11	2016-01-22	82.412 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		0.200 mi
Registration #20		11.777 est
Registration #21		11.777 mi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg
Additional information	
Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 16/16