



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D4 SE LUX
Colour	Grey
Year of manufacture	2016
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 4

Date 2021-07-30

Pictures 10

Listing price [View report](#)



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 3

Date 2021-07-29

Pictures 12

Listing price [View report](#)



source: [yesauto.com](https://www.yesauto.com)

Entry 2

Date 2021-07-28

Pictures 12

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1


Date 2021-07-27
CarCheck.co.uk

Pictures

12

Listing price

[View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-05
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #5 2023-09-04 16:35

MOT test number 435639582751

Result ✓ Passed

Next expiry date 2024-09-05

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm, out of shape and nail in tread (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm and out of shape (5.2.3 (e))

MOT #4 2022-08-26 11:34

MOT test number 477742060098

Result ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2021-09-06 06:51

MOT test number 137938609587

Result ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))



MOT #2	2020-10-06 08:07
MOT test number	267890477303
Result	✓ Passed

MOT #1	2019-10-07 09:08
MOT test number	189292560068
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KN66PZV
Plate since	2019-09-29
Current registration	KN66PZV
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-18
Last registration	2023-09-04
Complete history	See info



Registration #1	2016-10-18	12 mi
Registration #2	2019-10-07	38.360 mi
Registration #3	2020-10-06	46.011 mi
Registration #4	2023-09-04	55.277 mi
Registration #5	2023-09-04	55.277 mi
Registration #6	2023-09-04	55.277 mi
Registration #7	2023-09-04	55.277 mi
Registration #8	2023-09-04	55.277 mi
Registration #9	2023-09-04	55.277 mi
Registration #10	2023-09-04	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4854 mm
Wheel base	2835 mm
Kerb weight	1679 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1488981