



report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Blue
Year of manufacture	-
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2023-09-24 11:41
MOT test number	916403618741
Result	✓ Passed
Next expiry date	2024-09-24
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2023-09-24 11:41
MOT test number	266847640234
Result	✗ Failed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2022-09-25 14:51

MOT test number

654127772227

Result

✓ Passed

Minor

Front Headlamp lens slightly defective both (4.1.1 (b) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17

2022-09-25 14:51

MOT test number

825926580982

Result

✗ Failed

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Front Headlamp lens slightly defective both (4.1.1 (b) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16

2021-08-24 14:13

MOT test number

661463187963

Result

✓ Passed

Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Brake pedal wearing smooth (1.1.2 (c))

**MOT #15**

2021-08-20 14:16

MOT test number

490238281805

Result**✗ Failed**

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #14

2020-09-30 12:00

MOT test number

827413496668

Result**✓ Passed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13**

2020-09-30 08:58

MOT test number

441137388357

Result

✗ Failed

- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

MOT #12

2019-11-25 10:33

MOT test number

268585972596

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2018-12-15 15:08

MOT test number

310390726803

Result

✓ Passed

MOT #10

2018-02-21 10:42

MOT test number

316366412141

Result

✓ Passed

- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Tyre starting to perish.
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #9** 2017-02-23 09:41**MOT test number** 149904998557**Result** ✓ Passed

- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2016-02-22 12:14**MOT test number** 635233160056**Result** ✓ Passed

- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2015-02-25 12:32**MOT test number** 645906555029**Result** ✓ Passed**MOT #6** 2014-02-20 14:00**MOT test number** 825301154076**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-02-18 11:10**MOT test number** 919469143086**Result** ✓ Passed**MOT #4** 2012-02-17 10:20**MOT test number** 858918442021**Result** ✓ Passed**MOT #3** 2011-02-25 10:22**MOT test number** 478586351038**Result** ✓ Passed**Notice** Front brake discs worn and rusted**MOT #2** 2010-03-06 10:51**MOT test number** 954775160073**Result** ✓ Passed**MOT #1** 2010-02-25 10:28**MOT test number** 801876050050**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-04-11
Last registration	2023-09-24
Complete history	See info



Registration #1	2007-04-11	28 mi
Registration #2	2010-02-25	56.678 mi
Registration #3	2010-03-06	57.338 mi
Registration #4	2011-02-25	62.940 mi
Registration #5	2012-02-17	66.380 mi
Registration #6	2013-02-18	69.955 mi
Registration #7	2014-02-20	73.554 mi
Registration #8	2015-02-25	76.930 mi
Registration #9	2016-02-22	81.307 mi
Registration #10	2017-02-23	85.194 mi
Registration #11	2018-02-21	88.221 mi
Registration #12	2019-02-22	91.250 mi
Registration #13	2020-02-23	94.279 mi
Registration #14	2021-02-24	97.308 mi
Registration #15	2022-02-25	100.337 mi
Registration #16	2023-02-26	103.366 mi
Registration #17	2024-02-27	106.395 mi
Registration #18	2025-02-28	109.424 mi
Registration #19	2026-02-29	112.453 mi
Registration #20	2027-03-01	115.482 mi
Registration #21	2028-03-02	118.511 mi
Registration #22	2029-03-03	121.540 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7L05452