



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	White
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2024-11-24
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	23
Total items failed	2

MOT #8	2023-11-20 16:41
MOT test number	467570962378
Result	✓ Passed
Next expiry date	2024-11-24

MOT #7	2022-11-25 16:45
MOT test number	581860833239
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2021-10-29 13:41
MOT test number	172095028466
Result	✓ Passed

MOT #5	2020-09-18 13:40
MOT test number	375947578968
Result	✓ Passed

**MOT #4**

2019-09-23 15:20

MOT test number

768456671992

Result

✓ Passed

- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Brake pedal slightly sinks under pressure but not to the floor
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

2019-09-19 14:40

MOT test number

541697187417

Result

✗ Failed

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Outer Tyre has ply or cords exposed tyre wall. (5.2.3 (d) (ii))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))



MOT #2	2018-09-19 11:21
MOT test number	248525197940
Result	✓ Passed
Minor	Offside Front Obligatory mirror slightly loose (3.3 (b) (i))

MOT #1	2017-08-30 11:42
MOT test number	546941770867
Result	✓ Passed
Advice	Offside Front wiper blade slightly split but still clearing screen
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Nail in tyre
Advice	Nearside Front Inner cv boot clip leaking grease
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Nail in tyre



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-09-24
Last registration	2023-11-20
Complete history	See info



Registration #1	2014-09-24	27 mi
Registration #2	2017-08-30	15.667 mi
Registration #3	2018-09-19	25.821 mi
Registration #4	2019-09-19	33.991 mi
Registration #5	2019-09-23	34.207 mi
Registration #6	2019-09-23	34.207 mi
Registration #7	2019-09-23	34.207 mi
Registration #8	2019-09-23	34.207 mi
Registration #9	2019-09-23	34.207 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1754073