




report date: 2024-03-28

## General information

Make	VOLVO
Model	V60 D2 CROSS COUNTRY PRO
Colour	Black
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-03-10
<b>MOT pass rate</b>	60 %
<b>MOT passed</b>	3
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	9
<b>Total items failed</b>	3

<b>MOT #5</b>	2023-03-10 15:15
<b>MOT test number</b>	184370958719
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-03-10
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #4</b>	2023-03-09 11:49
<b>MOT test number</b>	258197267234
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #3</b>	2022-03-11 16:10
<b>MOT test number</b>	219161586878
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt o/s and n/s rear



MOT #2	2022-03-11 14:00
MOT test number	329305450698
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt o/s and n/s rear
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #1	2021-03-09 15:23
MOT test number	791843353690
Result	✓ Passed
Advice	Under trays fitted obscuring full inspection
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 March 2025

✗  
**MOT**  
  
Expired:  
10 March 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX18LWD
Plate since	2019-09-29
Current registration	YX18LWD
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-09
Last registration	2023-03-10
Complete history	<a href="#">See info</a>



Registration #1	2018-03-09	26 mi
Registration #2	2019-03-09	26.377 mi
Registration #3	2021-03-09	27.038 mi
Registration #4	2022-03-11	35.765 mi
Registration #5	2023-03-10	35.765 mi
Registration #6	2023-03-10	35.765 mi
Registration #7	2023-03-10	35.765 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1470 mm
Length	4370 mm
Wheel base	2646 mm
Kerb weight	1450 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

2447172