



PJ59BVB

report date: 2024-03-28

General information

Make	FIAT
Model	FIORINO 8V
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-07-01
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	11

MOT #13	2023-01-25 09:29
MOT test number	660975926600
Result	✓ Passed
Next expiry date	2024-01-24
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-11-20 08:17
MOT test number	851136698982
Result	✓ Passed

**MOT #11**

2021-11-18 14:28

**MOT test number**

354820927235

**Result****✗ Failed**

- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #10**

2020-12-11 08:58

**MOT test number**

833373996142

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm 175/70/14c (5.2.3 (e))
- Advice** Fuel tank corroded
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn t 2.5mm (5.2.3 (e))

**MOT #9** 2020-12-10 12:59**MOT test number** 453681577123**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Fuel tank corroded**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm 175/70/14c (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn t 2.5mm (5.2.3 (e))**MOT #8** 2019-12-09 14:03**MOT test number** 820572658931**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-06-05 11:52**MOT test number** 278407148986**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2017-04-22 11:51**MOT test number** 263871024243**Result** ✓ Passed**MOT #5** 2016-02-23 08:47**MOT test number** 341512460305**Result** ✓ Passed

**MOT #4** 2015-03-06 11:29**MOT test number** 387515665026**Result** ✓ Passed**MOT #3** 2014-03-07 08:51**MOT test number** 687256264033**Result** ✓ Passed**MOT #2** 2013-01-08 10:50**MOT test number** 428768503050**Result** ✓ Passed

**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Notice** Knock from front on off side and near side when traveling over bumps

**MOT #1** 2012-11-28 12:13**MOT test number** 608413132332**Result** ✗ Failed

**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)

**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

**Fail** Nearside Front Mechanical brake component has restricted free movement (3.5.1k)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✗  
**MOT**  
**Expired:**  
24 January 2024


Tax status		Valid until 1 October
Days left		155
MOT expiry date		24 January 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-15
Last registration	2023-01-25
Complete history	<a href="#">See info</a>



Registration #1	2009-12-15	26 mi
Registration #2	2012-11-28	34.935 mi
Registration #3	2013-01-08	34.940 mi
Registration #4	2014-03-07	52.166 mi
Registration #5	2015-03-06	70.152 mi
Registration #6	2016-02-23	87.570 mi
Registration #7	2017-04-22	99.480 mi
Registration #8	2018-06-05	102.675 mi
Registration #9	2019-05-20	103.377 mi
Registration #10	2020-05-20	103.377 mi
Registration #11	2021-05-20	103.377 mi
Registration #12	2022-05-20	103.377 mi
Registration #13	2023-05-20	103.377 mi
Registration #14	2024-05-20	103.377 mi
Registration #15	2025-05-20	103.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Engine number	5929618