





report date: 2024-03-29

#### General information

Make	MAZDA
Model	MX-5 ICON
Colour	Grey
Year of manufacture	2016
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	129 BHP
Max. torque	150 Nm at 4.800 rpm
Engine capacity	1.496 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 3

Date 2022-01-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date 2021-12-18

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-08-28

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



AV66CWL report date: 2024-03-29

MOT history

MOT expiry date	2024-12-13
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #6		2023-11-29 10:28
MOT test	number	637442710394
Result		✓ Passed
Next exp	iry date	2024-12-13
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or li	ght sources (4.7.1 (b)
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2022-11-23 14:15
MOT test number	380163315349
Result	✓ Passed
MOT #4	2021-12-14 17:37
MOT test number	447216909459
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2020-10-29 12:13

**MOT test number** 395708968223

Minor Central Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing Tyre also wearing on outer edge. (5.2.3

(d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing Tyre also wearing on outer edge.

(5.2.3 (d) (ii))

**MOT #2** 2019-10-28 17:16

**MOT test number** 579320177742

**Result** ✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view chip in windscreen passenger side (3.2 (a) (i))

MOT #1 2019-10-28 17:16

MOT test number 820518121776

**Result** X Failed

**Minor** Windscreen damaged but not adversely affecting driver's view chip in windscreen passenger side (3.2 (a) (i))

Pass with rectification Windscreen wiper does not clear the windscreen effectively both fronts (3.4 (b) (ii))

CarCheck.co.uk page 4/11



AV66CWL report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	13 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

e mier metery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
**************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



**AV66CWL** report date: 2024-03-29

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



AV66CWL report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-31
Last registration	2023-11-29
Complete history	See info



Registration #1	2016-10-31	7 mi
Registration #2	2019-10-28	53.172 mi
Registration #3	2019-10-28	53.172 mi
Registration #4	2020-10-29	57.877 mi
Registration #5		11.177 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1735 mm
Height	1225 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	975 kg
Max. allowed weight	1215 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	P5 30233459

CarCheck.co.uk page 11/11