



General information

Make	VOLKSWAGEN
Model	CARAVELLE T32 TDI W/V
Colour	Black
Year of manufacture	2010
Top speed	114 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-04-06
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	9

MOT #17	2024-04-02 16:14
MOT test number	188010351647
Result	✓ Passed
Next expiry date	2025-04-06

MOT #16	2023-04-05 09:49
MOT test number	771918176090
Result	✓ Passed
Advice	Rear unable to check rear seats or belts

MOT #15	2023-04-04 15:15
MOT test number	401989256392
Result	✗ Failed
Advice	Rear unable to check rear seats or belts
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #14	2022-04-06 14:22
MOT test number	920112073533
Result	✓ Passed

**MOT #13** 2022-04-06 10:00**MOT test number** 779472411598**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 235/55 17 (5.2.3 (e))**MOT #12** 2021-04-07 15:03**MOT test number** 453728113051**Result** ✓ Passed**Advice** Nearside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside exhaust outer skin corroded both boxes**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-11-27 08:44**MOT test number** 325555717631**Result** ✓ Passed**MOT #10** 2019-11-21 15:57**MOT test number** 239425987779**Result** ✗ Failed**Fail** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**MOT #9** 2018-12-15 12:20**MOT test number** 474610065856**Result** ✓ Passed

**MOT #8** 2018-12-13 15:05**MOT test number** 499208636780**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear high level brake lamp broken**MOT #7** 2018-01-11 16:28**MOT test number** 235933448348**Result** ✓ Passed**MOT #6** 2017-02-01 16:25**MOT test number** 610878601557**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2017-02-01 14:43**MOT test number** 175586534848**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



<b>MOT #4</b>	2016-02-18 12:08
---------------	------------------

<b>MOT test number</b>	776977575141
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear cut on tyre wall
---------------	-------------------------------

<b>MOT #3</b>	2015-03-23 14:10
---------------	------------------

<b>MOT test number</b>	516802285018
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-05-27 09:16
---------------	------------------

<b>MOT test number</b>	249217244481
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear registration plate delaminated but not likely to be misread (6.3.1d)
---------------	---

<b>MOT #1</b>	2013-06-26 11:19
---------------	------------------

<b>MOT test number</b>	357737473107
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
6 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	6 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SW10DFG</b>
Plate since	2024-03-29
Current registration	 <b>SW10DFG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-29
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2010-06-29	20 mi
Registration #2	2013-06-26	20.056 mi
Registration #3	2014-05-27	25.537 mi
Registration #4	2015-03-23	30.633 mi
Registration #5	2016-02-18	35.134 mi
Registration #6	2017-02-01	39.206 mi
Registration #7	2017-02-01	39.208 mi
Registration #8	2018-01-11	44.402 mi
Registration #9	2018-12-13	47.781 mi
Registration #10	2018-12-15	47.782 mi
Registration #11	2019-01-01	48.000 mi
Registration #12	2019-01-01	48.000 mi
Registration #13	2019-01-01	48.000 mi
Registration #14	2019-01-01	48.000 mi
Registration #15	2019-01-01	48.000 mi
Registration #16	2019-01-01	48.000 mi
Registration #17	2019-01-01	48.000 mi
Registration #18	2019-01-01	48.000 mi
Registration #19	2019-01-01	48.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2283 mm
Height	2176 mm
Length	5292 mm
Kerb weight	2029 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

**Engine number**

CFC005173