



HONDA



SY09ZKV


report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-DTEC EX GT
Colour	Red
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-02-24
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-29
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	11
Total items failed	3

MOT #13	2023-06-13 15:28
MOT test number	611763584058
Result	✓ Passed
Next expiry date	2024-06-29

MOT #12	2023-06-13 08:54
MOT test number	308608842760
Result	✗ Failed
Fail	Nearside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #11	2022-06-23 12:31
MOT test number	357694680381
Result	✓ Passed
Advice	Offside Rear handbrake cable split
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2021-06-28 08:14**MOT test number** 427321554382**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2020-06-30 10:46**MOT test number** 488464430593**Result** ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre wearing on inner edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre wearing on inner edge (5.2.3 (e))**MOT #8** 2019-03-06 13:15**MOT test number** 850430248446**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**MOT #7** 2018-03-09 16:11**MOT test number** 847594087802**Result** ✓ Passed**MOT #6** 2017-05-15 07:54**MOT test number** 172338185024**Result** ✓ Passed



<b>MOT #5</b>	2016-05-11 11:11
---------------	------------------

<b>MOT test number</b>	127045035254
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2015-05-26 16:11
---------------	------------------

<b>MOT test number</b>	149586545160
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2014-07-09 11:09
---------------	------------------

<b>MOT test number</b>	319880894181
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Notice** Nsr brake binding causing brake pads to wear quicker

<b>MOT #2</b>	2013-07-03 15:55
---------------	------------------

<b>MOT test number</b>	655954283160
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-07-18 14:49
---------------	------------------

<b>MOT test number</b>	279250502220
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
29 June 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	29 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>SY09ZKV</b>
Plate since	2019-09-29
Current registration	<b>SY09ZKV</b>
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-31
Last registration	2023-06-13
Complete history	<a href="#">See info</a>



Registration #1	2009-07-31	12 mi
Registration #2	2012-07-18	15.616 mi
Registration #3	2013-07-03	19.890 mi
Registration #4	2014-07-09	25.103 mi
Registration #5	2015-05-26	28.573 mi
Registration #6	2016-05-11	36.112 mi
Registration #7	2017-05-15	43.888 mi
Registration #8	2018-03-09	51.256 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi
Registration #15	2020-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22B11011562