



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | JAGUAR |
| Model | X-TYPE SE |
| Colour | Green |
| Year of manufacture | 2009 |
| Top speed | 125 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 145 BHP |
| Max. torque | 360 Nm at 1.800 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 29.7 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 184 g/km |
| CO2 label | I |






Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-07-23 |
| Pictures | 20 |
| Listing price | View report |



source: yesauto.com

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-22 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-10-14 |
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 5 |

| | |
|-------------------------|------------------|
| MOT #15 | 2023-09-28 13:33 |
| MOT test number | 531914052792 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-14 |

| | |
|------------------------|--|
| MOT #14 | 2023-09-23 08:58 |
| MOT test number | 668388921911 |
| Result | ✗ Failed |
| Fail | Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |
| Fail | Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) |
| Fail | Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |
| Advice | Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) |
| Fail | Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) |

| | |
|------------------------|------------------|
| MOT #13 | 2022-10-01 07:48 |
| MOT test number | 204231787608 |
| Result | ✓ Passed |

**MOT #12** 2022-09-30 11:02**MOT test number** 776112294599**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2021-10-15 11:55**MOT test number** 860500326242**Result** ✓ Passed**Advice** Some suspension components covered in black paint coating at rear**MOT #10** 2020-12-03 14:42**MOT test number** 830182493932**Result** ✓ Passed**Advice** Undertrays fitted**MOT #9** 2019-11-26 09:16**MOT test number** 772952029412**Result** ✓ Passed**Advice** Rear Shock absorbers has a slightly worn bush both rear lower shock absorber bushes perished (5.3.2 (c))**MOT #8** 2018-12-03 16:49**MOT test number** 180248496880**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-01-15 09:50**MOT test number** 368683872009**Result** ✓ Passed

**MOT #6** 2017-01-31 10:48**MOT test number** 168127292301**Result** ✓ Passed**Advice** Nearside Front tyre tread low on inner edge**MOT #5** 2016-01-28 08:49**MOT test number** 377092467555**Result** ✓ Passed**MOT #4** 2015-02-13 14:23**MOT test number** 268624145048**Result** ✓ Passed**MOT #3** 2014-09-08 16:37**MOT test number** 549811954299**Result** ✓ Passed**MOT #2** 2013-09-10 09:20**MOT test number** 758263353213**Result** ✓ Passed**MOT #1** 2012-09-14 14:13**MOT test number** 559928552228**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 14 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------|
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2009-09-29 |
| Last registration | 2023-09-28 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-09-29 | 24 mi |
| Registration #2 | 2012-09-14 | 31.311 mi |
| Registration #3 | 2013-09-10 | 34.006 mi |
| Registration #4 | 2014-09-08 | 37.415 mi |
| Registration #5 | 2015-02-13 | 38.675 mi |
| Registration #6 | 2016-01-28 | 44.039 mi |
| Registration #7 | 2017-01-31 | 50.207 mi |
| Registration #8 | 2018-01-15 | 60.963 mi |
| Registration #9 | 2018-12-03 | 69.435 mi |
| Registration #10 | 2019-05-29 | 75.277 mi |
| Registration #11 | 2019-05-29 | 75.277 mi |
| Registration #12 | 2019-05-29 | 75.277 mi |
| Registration #13 | 2019-05-29 | 75.277 mi |
| Registration #14 | 2019-05-29 | 75.277 mi |
| Registration #15 | 2019-05-29 | 75.277 mi |
| Registration #16 | 2019-05-29 | 75.277 mi |
| Registration #17 | 2019-05-29 | 75.277 mi |
| Registration #18 | 2019-05-29 | 75.277 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2003 mm |
| Height | 1483 mm |
| Length | 4716 mm |
| Wheel base | 2710 mm |
| Kerb weight | 1605 kg |
| Max. allowed weight | 2120 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 61 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 090622085755BG |