



BN06RJV

report date: 2024-03-28

General information

Make	NISSAN
Model	PRIMERA SX
Colour	Grey
Year of manufacture	-
Top speed	117 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-05
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #19	2021-12-31 15:19
MOT test number	810889628260
Result	✓ Passed
Next expiry date	2022-12-30
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #18	2021-12-31 15:19
MOT test number	456948071192
Result	✗ Failed
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #17	2020-11-05 17:46
MOT test number	398988405118
Result	✓ Passed
Advice	Oil leak, but not excessive Sump corroded (8.4.1 (a) (i))
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Power steering ram has slight seepage from a joint (2.1.5 (a))

**MOT #16**

2020-11-05 16:33

MOT test number

909225935545

Result**✗ Failed**

- Advice** Offside Power steering ram has slight seepage from a joint (2.1.5 (a))
- Fail** Rear Stop lamp(s) adversely affected by the operation of another lamp Both sides (4.3.3 (b))
- Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Advice** Oil leak, but not excessive Sump corroded (8.4.1 (a) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

MOT #15

2019-05-07 17:29

MOT test number

149645978391

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2019-05-07 17:29

MOT test number

863601681276

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #13** 2018-05-09 14:51**MOT test number** 646098842216**Result** ✓ Passed**Advice** O/s/f wheel stiff to rotate**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #12** 2017-05-03 16:15**MOT test number** 361174793225**Result** ✓ Passed**MOT #11** 2017-05-02 12:48**MOT test number** 740387195705**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #10** 2016-05-12 15:54**MOT test number** 972605909423**Result** ✓ Passed**MOT #9** 2016-05-10 14:36**MOT test number** 855651569657**Result** ✗ Failed**Fail** Fuel cap/sealing device does not fasten securely by positive means (7.2.4b)**MOT #8** 2015-05-13 18:38**MOT test number** 367593335116**Result** ✓ Passed

**MOT #7** 2015-05-13 14:55**MOT test number** 576443635153**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #6** 2014-03-04 09:49**MOT test number** 737373264006**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2013-03-06 10:43**MOT test number** 937245363031**Result** ✓ Passed**MOT #4** 2012-03-05 11:10**MOT test number** 448655462011**Result** ✓ Passed**MOT #3** 2011-03-08 10:18**MOT test number** 356487161049**Result** ✓ Passed**MOT #2** 2010-03-09 10:54**MOT test number** 141128960086**Result** ✓ Passed



MOT #1	2009-03-06 11:28
MOT test number	233465569009
Result	✓ Passed



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 BN06RJV
Plate since	2024-03-28
Current registration	 BN06RJV
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-09
Last registration	2021-12-31
Complete history	See info



Registration #1	2006-03-09	8 mi
Registration #2	2009-03-06	21.035 mi
Registration #3	2010-03-09	27.911 mi
Registration #4	2011-03-08	34.605 mi
Registration #5	2012-03-05	41.128 mi
Registration #6	2013-03-06	47.927 mi
Registration #7	2014-03-04	54.288 mi
Registration #8	2015-05-13	65.032 mi
Registration #9	2015-05-13	65.032 mi
Registration #10	2016-05-10	73.062 mi
Registration #11	2016-05-12	73.093 mi
Registration #12	2016-05-12	73.093 mi
Registration #13	2016-05-12	73.093 mi
Registration #14	2016-05-12	73.093 mi
Registration #15	2016-05-12	73.093 mi
Registration #16	2016-05-12	73.093 mi
Registration #17	2016-05-12	73.093 mi
Registration #18	2016-05-12	73.093 mi
Registration #19	2016-05-12	73.093 mi
Registration #20	2016-05-12	73.093 mi
Registration #21	2016-05-12	73.093 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1428 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1361 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	411803