





report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-DTEC EX GT
Colour	Silver
Year of manufacture	2009
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-26

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

2022-08-03 15:15

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT #13

MOT expiry date	2024-09-24
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #14	2023-09-25 14:49
MOT test number	633560525078
Result	✓ Passed
Next expiry date	2024-09-24

MOT test number	670710539170
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in excess arm front bush (5.3.4 (a) (i))	ssive movement lower

MOT #12	2021-08-02 14:52
MOT test number	592089337749
Result	✓ Passed

MOT #11	2020-12-18 09:12
MOT test number	220333707294
Result	✓ Passed

MOT #10	2019-10-26 10:57
MOT test number	573202469758
Result	✓ Passed
Advice Front wipers in poor condition	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2018-10-15 11:54

MOT test number 245905655898

Result \rightarrow Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front rubber bush splitting and perished (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front rubber bush splitting and perished (5.3.4 (a) (i))

MOT #8 2018-10-13 08:26

MOT test number 696204453508

Result X Failed

DANGEROUS Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Pass with rectification Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front rubber bush splitting and perished (5.3.4 (a) (i))

DANGEROUS Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front rubber bush splitting and perished (5.3.4 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #7 2017-10-14 08:45

MOT test number 724562656263

Result \(\sqrt{Passed} \)

Advice Battery loose in tray

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Battery terminal loose

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2016-10-17 14:05

MOT test number 901157350126

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5	2015-09-29 08:14
MOT test number	730125182540
Result	✓ Passed
MOT #4	2014-10-13 11:28
MOT test number	219376984296
Result	✓ Passed
MOT #3	2014-04-07 14:16
MOT test number	117887694081
Result	✓ Passed
Notice Items removed from driver's view prior to test Notice N/s/f and n/s/r tyres worn on outer sidewall	

	2013-04-09 15:33
number	779069093035
	✓ Passed
	2012-06-11 16:40
number	359523862186
	✓ Passed
Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Nail in nearside rear tyre	
Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
	number Offside Front Tyre worn close to the legal limit (4.1.E.1) Nail in nearside rear tyre

CarCheck.co.uk page 5/12



VN09BHL report date: 2024-03-29

Toport autor 20.

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manana and a same and	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	NIE NIE NIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-16
Last registration	2023-09-25
Complete history	See info



Registration #1	2009-06-16	12 mi
Registration #2	2012-06-11	38.911 mi
Registration #3	2013-04-09	44.955 mi
Registration #4	2014-04-07	49.478 mi
Registration #5	2014-10-13	51.469 mi
Registration #6	2015-09-29	60.977 mi
Registration #7	2016-10-17	61.008 mi
Registration #8	2017-10-14	72.782 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	N22B11006720

CarCheck.co.uk page 12/12