



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-06-20
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-30
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	10
Total items failed	13

MOT #19 2023-12-01 13:31

MOT test number 602131250282

Result ✓ Passed

Next expiry date 2024-11-30

Advice Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

Advice Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #18 2023-07-03 14:28

MOT test number 536878327757

Result ✓ Passed

Advice Nearside Front Lower SUSPENSION ARM BALL JOINT RUBBER SPLIT

MOT #17 2023-07-03 08:42

MOT test number 961060072078

Result ✗ Failed

Advice Nearside Front Lower SUSPENSION ARM BALL JOINT RUBBER SPLIT

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #16** 2022-06-27 09:16**MOT test number** 492096251541**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**MOT #15** 2022-06-27 09:16**MOT test number** 136113697270**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #14** 2021-07-14 13:17**MOT test number** 184410419835**Result** ✓ Passed**MOT #13** 2021-07-12 13:46**MOT test number** 615857220170**Result** ✗ Failed**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Offside Front Brake disc significantly and obviously worn inner edge (1.1.14 (a) (i))**MOT #12** 2020-06-24 11:17**MOT test number** 880807057355**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2019-07-18 14:48**MOT test number** 236755628804**Result** ✓ Passed**MOT #10** 2019-07-18 08:31**MOT test number** 605547453108**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2018-08-01 16:31**MOT test number** 158729041098**Result** ✓ Passed**MOT #8** 2018-08-01 08:39**MOT test number** 751903274062**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2017-07-19 08:15**MOT test number** 271154943800**Result** ✓ Passed**MOT #6** 2016-08-03 08:20**MOT test number** 495300174337**Result** ✓ Passed

**MOT #5** 2015-08-04 09:16**MOT test number** 675096715273**Result** ✓ Passed**MOT #4** 2014-07-31 09:39**MOT test number** 866782714234**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-07-26 09:57**MOT test number** 355537003225**Result** ✓ Passed**MOT #2** 2012-07-24 09:25**MOT test number** 839656002261**Result** ✓ Passed**MOT #1** 2011-08-16 09:47**MOT test number** 939878721206**Result** ✓ Passed**Notice** Nsf osf brake discs slight corrosion



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	GY09JLV
Plate since	2019-09-29
Current registration	GY09JLV
Plate since	2019-09-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-04-30
Last registration	2023-12-01
Complete history	See info



Registration #1	2009-04-30	10 mi
Registration #2	2011-08-16	20.733 mi
Registration #3	2012-07-24	27.199 mi
Registration #4	2013-07-26	33.387 mi
Registration #5	2014-07-31	39.935 mi
Registration #6	2015-08-04	45.990 mi
Registration #7	2016-08-03	50.792 mi
Registration #8	2017-07-19	54.936 mi
Registration #9	2018-08-01	58.811 mi
Registration #10	2018-08-01	58.811 mi
Registration #11	2019-07-18	64.141 mi
Registration #12	2020-05-20	65.277 mi
Registration #13	2020-05-20	65.277 mi
Registration #14	2020-05-20	65.277 mi
Registration #15	2020-05-20	65.277 mi
Registration #16	2020-05-20	65.277 mi
Registration #17	2020-05-20	65.277 mi
Registration #18	2020-05-20	65.277 mi
Registration #19	2020-05-20	65.277 mi
Registration #20	2020-05-20	65.277 mi
Registration #21	2020-05-20	65.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630637445