



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	AGILA CLUB AC
Colour	Blue
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-09
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-04-18
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	14
<b>Total items failed</b>	9

**MOT #15** 2022-04-19 11:11**MOT test number** 492135103112**Result** Passed**Next expiry date** 2023-04-18

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14** 2021-08-06 12:01**MOT test number** 960921044933**Result** Passed

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #13**

2021-07-27 15:15

**MOT test number**

124615630167

**Result****✗ Failed****Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12**

2020-08-17 13:53

**MOT test number**

734111326880

**Result****✓ Passed****MOT #11**

2019-08-24 11:05

**MOT test number**

117165290361

**Result****✓ Passed****Advice** Both front upper strut mounts have play but not excessive**MOT #10**

2018-08-16 13:11

**MOT test number**

496736998654

**Result****✓ Passed**

**MOT #9** 2018-08-15 08:23**MOT test number** 253722882762**Result** ✗ Failed**Fail** Nearside Front Road wheel badly distorted (5.2.2 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 185/60x15 (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and small cut in tread to cord (5.2.3 (e))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #8** 2017-08-07 16:04**MOT test number** 634779386083**Result** ✓ Passed**MOT #7** 2017-08-07 08:40**MOT test number** 842332717720**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #6** 2016-08-02 13:03**MOT test number** 825456746214**Result** ✓ Passed



<b>MOT #5</b>	2015-07-20 09:29
---------------	------------------

<b>MOT test number</b>	585621005299
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>MOT #4</b>	2014-07-26 07:40
---------------	------------------

<b>MOT test number</b>	425897904271
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-07-27 07:33
---------------	------------------

<b>MOT test number</b>	485878103264
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-08-17 17:27
---------------	------------------

<b>MOT test number</b>	849280832235
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2011-08-19 07:52
---------------	------------------

<b>MOT test number</b>	168981031221
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2023

X

MOT

Expired:  
18 April 2023

Tax status	Expired at 1 April 2023
Days left	394 days too late
MOT expiry date	18 April 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>HJ58XJN</b>
Plate since	2019-03-29
Current registration	 <b>HJ58XJN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-26
Last registration	2022-04-19
Complete history	<a href="#">See info</a>



Registration #1	2008-09-26	17 mi
Registration #2	2011-08-19	22.084 mi
Registration #3	2012-08-17	28.687 mi
Registration #4	2013-07-27	36.238 mi
Registration #5	2014-07-26	41.371 mi
Registration #6	2015-07-20	49.324 mi
Registration #7	2016-08-02	54.673 mi
Registration #8	2017-08-07	61.314 mi
Registration #9	2017-08-07	61.314 mi
Registration #10	2019-05-20	75.377 mi
Registration #11	2019-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2019-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2019-05-20	75.377 mi
Registration #16	2019-05-20	75.377 mi
Registration #17	2019-05-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1000 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1096292