



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Blue
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg





LABEL UNKNOWN



Internet history

Entry 2



Date	2022-02-20
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-02-19
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #14</b>	2022-08-01 11:21
<b>MOT test number</b>	117133238292
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-08-01
<b>Advice</b>	Items removed from driver's view prior to test
<b>Advice</b>	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

<b>MOT #13</b>	2021-08-02 15:53
<b>MOT test number</b>	100982749042
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases flexi joint (6.1.2 (a))

<b>MOT #12</b>	2021-07-27 09:01
<b>MOT test number</b>	801312774661
<b>Result</b>	✗ Failed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Fail</b>	Offside Obligatory mirror missing (3.3 (a))
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases flexi joint (6.1.2 (a))

<b>MOT #11</b>	2020-07-02 15:05
<b>MOT test number</b>	942959291628
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))



<b>MOT #10</b>	2019-07-15 08:18
<b>MOT test number</b>	615855368586
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #9</b>	2018-07-18 13:24
<b>MOT test number</b>	123180249129
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
<b>Advice</b>	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #8</b>	2017-07-19 10:12
<b>MOT test number</b>	348419156210
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front coil spring corroded (2.4.C.1b)

<b>MOT #7</b>	2016-07-26 08:46
<b>MOT test number</b>	817148267608
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2015-07-21 12:56
<b>MOT test number</b>	805332905234
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2014-07-28 17:15
<b>MOT test number</b>	699819904207
<b>Result</b>	✓ Passed



MOT #4	2013-08-29 12:29
MOT test number	218331343219
Result	✓ Passed

MOT #3	2012-09-21 11:29
MOT test number	899155362246
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-09-23 09:08
MOT test number	246076061273
Result	✓ Passed

MOT #1	2010-09-23 10:49
MOT test number	142156060269
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nail in offside rear tyre
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nail in nearside rear tyre



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	HV57VLN
Plate since	2019-06-29
Current registration	HV57VLN
Plate since	2019-06-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-28
Last registration	2022-08-01
Complete history	<a href="#">See info</a>



Registration #1	2007-09-28	15 mi
Registration #2	2010-09-23	21.030 mi
Registration #3	2011-09-23	28.274 mi
Registration #4	2012-09-21	36.118 mi
Registration #5	2013-08-29	42.987 mi
Registration #6	2014-07-28	44.560 mi
Registration #7	2015-07-21	47.651 mi
Registration #8	2016-07-26	50.746 mi
Registration #9	2017-07-19	54.071 mi
Registration #10	2018-08-01	55.377 mi
Registration #11	2019-08-01	55.377 mi
Registration #12	2020-08-01	55.377 mi
Registration #13	2021-08-01	55.377 mi
Registration #14	2022-08-01	55.377 mi
Registration #15	2023-08-01	55.377 mi
Registration #16	2024-03-28	55.377 mi
Registration #17	2024-03-28	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118