





General information

| Make | CITROEN |
|---------------------|------------------|
| Model | C4 BLUEHDI FLAIR |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 114 mph |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 98 BHP |
|-------------------------|---------------------|
| Max. torque | 254 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 85.6 mpg |
| Consumption combined | 78.5 mpg |
| CO2 emission | 95 g/km |
| CO2 label | А |








| 2022-07-23 |
|-------------|
| 1 |
| View report |
| |



source: cargurus.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-06-04 |
| Pictures | 43 |
| Listing price | View report |
| | |



source: yesauto.com



MOT history

| MOT expiry date | 2024-06-29 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 8 |
| Total items failed | 4 |

| MOT #8 | | 2023-06-15 15:32 |
|--|---|------------------|
| MOT test n | umber | 959206423215 |
| Result | | ✓ Passed |
| Next expiry | y date | 2024-06-29 |
| Advice | Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

MOT #7 2023-06-15 14:09 MOT test mber 777859138762 Result Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

| MOT #6 | 2022-06-16 15:15 |
|-----------------|------------------|
| MOT test number | 879953796139 |
| Result | ✓ Passed |





| MOT #5 | 2021-06-16 15:06 |
|--|----------------------------|
| MOT test number | 587005048830 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2021-06-14 11:45 |
| MOT test number | 531451103993 |
| Result | × Failed |
| Fail Rear Exhaust system insecure (6.1.2 (a)) | |
| Advice COOLANT LEVEL LOW | |
| Fail Fluid leak harmful to the environment or a risk to other road users RADIATC | OR COOLANT (8.4.1 (a) (i)) |

| МОТ #3 | 2020-06-03 08:13 |
|-----------------|------------------|
| MOT test number | 610184585943 |
| Result | ✓ Passed |

| MOT #2 | | 2020-06-03 08:13 |
|-------------------------|---|------------------|
| MOT test number | | 240797753806 |
| Result | | 🗙 Failed |
| Pass with rectification | Windscreen washer not working (3.5 (a)) | |

| MOT #1 | 2019-06-08 07:56 |
|----------------------------------|------------------|
| MOT test number | 733444942226 |
| Result | ✓ Passed |
| Advice Offside Rear Nail in tyre | |



Tax & MOT check

| Taxed Tax due: 1 August 2024 | ✓ MOT Expires: 29 June 2024 |
|------------------------------------|--------------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 29 June 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |
| Vehicle class | 49 |
| Band | А |

| Single payment (12 months) | £ 0,00,- |
|---|----------------|
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | Law P |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E CAT D |
| Date | ₩. |
| Category | AMPT |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2016-06-30 |
| Last registration | 2023-06-15 |
| Complete history | See info |



| Registration #1 | 2016-06-30 | 28 mi |
|------------------------------------|------------|---|
| Registration #2 | 2019-06-08 | 43.688 mi |
| Registration #3 | 2020-06-03 | 49.309 mi |
| Registration #4 | 2020-06-03 | 49.309 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | 2021-06-14 | 54.411 mi |
| | | |
| Registration #7 | | 11.777 est |
| Registration #7 Registration #8 | | 10.000 est |
| - | | 00.000 est 0.000 est 00.000 est |
| Registration #8 | | 00.000 est 0.000 est 00.000 est 00.000 est |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 85% |
| Pedestrian | 43% |
| Safety systems | 97% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1729 mm |
| Height | 1480 mm |
| Length | 4157 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1068 kg |
| Max. allowed weight | 1610 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 45 |
| | 45 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |