




General information

Make	NISSAN
Model	ALMERA SE TINO
Colour	Silver
Year of manufacture	2005
Top speed	108 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-27
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-21
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	43
Total items failed	8

MOT #24	2024-03-22 09:35
MOT test number	734860806219
Result	✓ Passed
Next expiry date	2025-03-21
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #23	2024-01-08 09:43
MOT test number	876243008211
Result	✗ Failed
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22** 2023-01-23 11:48**MOT test number** 230213428436**Result** ✓ Passed**MOT #21** 2022-02-11 12:27**MOT test number** 819381064686**Result** ✓ Passed**Advice** Underbody covered in underseal**MOT #20** 2022-02-11 12:27**MOT test number** 142300561343**Result** ✗ Failed**Pass with rectification** Rear Exhaust system insecure (6.1.2 (a))**Advice** Underbody covered in underseal**MOT #19** 2021-09-03 12:30**MOT test number** 184409040338**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #18** 2021-09-03 09:03**MOT test number** 467008706864**Result** ✗ Failed**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**MOT #17** 2020-09-03 09:09**MOT test number** 105068324304**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #16** 2019-09-05 07:47**MOT test number** 904837407927**Result** ✓ Passed**MOT #15** 2019-09-04 10:00**MOT test number** 103852836451**Result** ✗ Failed**DANGEROUS** Nearside Rear Outer Tyre has ply or cords exposed wall (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Outer Tyre has ply or cords exposed wall (5.2.3 (d) (ii))

**MOT #14**

2018-08-22 10:30

MOT test number

215955607516

Result

✓ Passed

Advice Scuttle panel is corroded and holed**Minor** Offside Headlamp lens slightly defective frosted (4.1.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Headlamp lens slightly defective frosted (4.1.1 (b) (i))**MOT #13**

2017-08-22 14:50

MOT test number

265242310841

Result

✓ Passed

Advice Nearside rear tyre sidewall damaged**MOT #12**

2017-08-22 10:38

MOT test number

313609416261

Result

✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear rear brake binding (3.7.B.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside rear tyre sidewall damaged**MOT #11**

2016-08-26 15:20

MOT test number

554142408610

Result

✓ Passed

Advice Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2016-08-26 09:24**MOT test number** 999869170622**Result** ✗ Failed

- Advice** Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

MOT #9 2015-08-28 10:56**MOT test number** 326402221150**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside head light lense cloudy
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #8 2014-08-28 10:04**MOT test number** 397410144423**Result** ✓ Passed**MOT #7** 2013-08-27 09:38**MOT test number** 478289333201**Result** ✓ Passed

- Notice** Windscreen marked

MOT #6 2012-08-28 12:02**MOT test number** 356801742439**Result** ✓ Passed

**MOT #5** 2011-08-31 12:00**MOT test number** 567613241296**Result** ✓ Passed**MOT #4** 2010-08-24 10:06**MOT test number** 154996030218**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2009-09-01 17:05**MOT test number** 861534849291**Result** ✓ Passed**Advice** Offside Front brake disc slightly scored (3.5.1h)**MOT #2** 2009-09-01 15:13**MOT test number** 320184749219**Result** ✗ Failed**Fail** Offside Rear brake disc excessively scored (3.5.1h)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front brake disc slightly scored (3.5.1h)**MOT #1** 2008-08-29 15:45**MOT test number** 540032248280**Result** ✓ Passed**Advice** Front brake disc slightly scored (3.5.1h)**Advice** Rear brake disc slightly scored (3.5.1h)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
21 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-09-02
Last registration	2024-03-22
Complete history	See info



Registration #1	2005-09-02	27 mi
Registration #2	2008-08-29	15.044 mi
Registration #3	2009-09-01	19.651 mi
Registration #4	2009-09-01	19.652 mi
Registration #5	2010-08-24	23.974 mi
Registration #6	2011-08-31	27.521 mi
Registration #7	2012-08-28	29.954 mi
Registration #8	2013-08-27	31.595 mi
Registration #9	2014-08-28	33.450 mi
Registration #10	2015-08-28	34.784 mi
Registration #11	2016-08-26	36.051 mi
Registration #12	2016-08-26	36.054 mi
Registration #13	2017-08-22	37.048 mi
Registration #14	2018-08-22	38.042 mi
Registration #15	2019-08-22	39.036 mi
Registration #16	2020-08-22	40.030 mi
Registration #17	2021-08-22	41.024 mi
Registration #18	2022-08-22	42.018 mi
Registration #19	2023-08-22	43.012 mi
Registration #20	2024-03-22	44.006 mi
Registration #21	2024-03-22	44.006 mi
Registration #22	2024-03-22	44.006 mi
Registration #23	2024-03-22	44.006 mi
Registration #24	2024-03-22	44.006 mi
Registration #25	2024-03-22	44.006 mi
Registration #26	2024-03-22	44.006 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1758 mm
Height	1608 mm
Length	4264 mm
Wheel base	2535 mm
Kerb weight	1420 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	404380