





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|----------------|
| Model | NOTE ACENTA |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 80 BHP |
|-------------------------|---------------------|
| Max. torque | 110 Nm at 4.000 rpm |
| Engine capacity | 1.198 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 109 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



Internet history

| | | 1 |
|---|------|---|
| ᆮ | HLIV | - |

| LIICI Y I | |
|---------------|-------------|
| Date | 2021-11-07 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/11



2022-07-05 10:46

MOT history

MOT #5

| MOT expiry date | 2024-08-31 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 1 |

| MOT #6 | | 2023-09-01 08:41 |
|------------|---|------------------|
| MOT test i | number | 914458897461 |
| Result | | ✓ Passed |
| Next expir | y date | 2024-08-31 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 3.1 - 2.9 - 3 mm | (5.2.3 (e)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing cracks in tread | (5.2.3 (d) (ii)) |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing cracks in tread (| 5.2.3 (d) (ii)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing cracks in tread (5 | 5.2.3 (d) (ii)) |

| MOT test | number | 138050540165 |
|----------|---|------------------|
| Result | | ✓ Passed |
| | | |
| MOT #4 | | 2021-07-13 12:49 |
| MOT test | number | 554979763292 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



AY66WFX

report date: 2024-03-29

| MOT #3 | 2020-07-28 13:27 |
|--|------------------|
| MOT test number | 953385313523 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2019-08-13 12:23 |
| MOT test number | 136786658961 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2019-08-13 11:35 |
| MOT test number | 327041718726 |
| Result | X Failed |
| Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i)) | |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 216 |
| MOT expiry date | 31 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 5/11



AY66WFX

report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|-------------|
| *************************************** | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | NK SIE |
| Plate since | |
| Current registration | NK NE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-09-02 |
| Last registration | 2023-09-01 |
| Complete history | See info |



| Registration #1 | 2016-09-02 | 6 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-08-13 | 10.587 mi |
| Registration #3 | 2019-08-13 | 10.587 mi |
| Registration #4 | 2020-07-28 | 12.294 mi |
| Registration #5 | | 9.70 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 82% |
| Pedestrian | 58% |
| Safety systems | 70% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1695 mm |
|---------------------|---------|
| Height | 1530 mm |
| Length | 4100 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1040 kg |
| Max. allowed weight | 1510 kg |

Additional information

| Fuel tank capacity | 41 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles 2

Engine number 105059R