



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Grey
Year of manufacture	2007
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-27
Pictures	29
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-03
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	36
Total items failed	12

MOT #22	2023-04-04 14:32
MOT test number	587455637886
Result	✓ Passed
Next expiry date	2024-04-03
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #21	2022-09-12 16:06
MOT test number	543164289767
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2022-09-08 16:47

MOT test number

739846942963

Result**✗ Failed**

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19

2021-08-18 14:58

MOT test number

229795594644

Result**✓ Passed****MOT #18**

2021-08-06 13:09

MOT test number

407496885979

Result**✗ Failed**

- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside side repeater lens slightly damaged, not affecting light output
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Non obligatory mirror damaged

MOT #17

2020-09-08 17:18

MOT test number

428185538978

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #16**

2019-09-10 10:28

MOT test number

591516700314

Result

✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #15**

2019-09-06 09:09

MOT test number

320652622369

Result

✗ Failed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Offside Rear Seat belt buckle damaged (7.1.2 (d))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #14**

2018-08-28 11:26

MOT test number

395788318835

Result

✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #13** 2018-08-28 10:00**MOT test number** 130594758956**Result** ✗ Failed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2017-09-11 15:08**MOT test number** 402795587166**Result** ✓ Passed

- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #11 2017-09-11 09:31**MOT test number** 393123443648**Result** ✗ Failed

- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #10 2016-08-15 15:55**MOT test number** 368111168063**Result** ✓ Passed

**MOT #9** 2016-08-15 08:20**MOT test number** 691967096623**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-09-14 09:35**MOT test number** 570015551669**Result** ✓ Passed**MOT #7** 2014-09-12 10:20**MOT test number** 607265154206**Result** ✓ Passed**Notice** Front wipers starting to smear**MOT #6** 2014-09-11 15:13**MOT test number** 579454754217**Result** ✗ Failed**Notice** Front wipers starting to smear**Fail** Fuel system component leaking (7.2.3)**MOT #5** 2013-09-11 12:29**MOT test number** 529494253263**Result** ✓ Passed



MOT #4	2012-09-13 11:13
MOT test number	705907052234
Result	✓ Passed
MOT #3	2011-09-01 14:04
MOT test number	829074941277
Result	✓ Passed
MOT #2	2011-09-01 10:57
MOT test number	716454841295
Result	✗ Failed
Fail	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
MOT #1	2010-08-26 12:27
MOT test number	290418930293
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✗
MOT

Expired:
3 April 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	3 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<div><div><div><div></div><div>UK</div></div><div>XXXXXX</div></div></div>
Plate since	2019-06-29
Current registration	<div><div><div><div></div><div>UK</div></div><div>XXXXXX</div></div></div>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-09-04
Last registration	2023-04-04
Complete history	See info



Registration #1	2007-09-04	6 mi
Registration #2	2010-08-26	23.436 mi
Registration #3	2011-09-01	34.684 mi
Registration #4	2011-09-01	34.684 mi
Registration #5	2012-09-13	44.668 mi
Registration #6	2013-09-11	52.918 mi
Registration #7	2014-09-11	58.924 mi
Registration #8	2014-09-12	58.924 mi
Registration #9	2015-09-14	66.858 mi
Registration #10	2016-08-15	72.454 mi
Registration #11	2016-08-15	72.454 mi
Registration #12	2017-09-11	80.639 mi
Registration #13	2018-09-11	80.639 mi
Registration #14	2018-09-11	80.639 mi
Registration #15	2018-09-11	80.639 mi
Registration #16	2018-09-11	80.639 mi
Registration #17	2018-09-11	80.639 mi
Registration #18	2018-09-11	80.639 mi
Registration #19	2018-09-11	80.639 mi
Registration #20	2018-09-11	80.639 mi
Registration #21	2018-09-11	80.639 mi
Registration #22	2018-09-11	80.639 mi
Registration #23	2018-09-11	80.639 mi
Registration #24	2018-09-11	80.639 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE 371313