



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I20 CLASSIC
Colour	White
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-31
Pictures	9
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-04-19
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	11
Total items failed	7

MOT #12	2024-04-16 08:39
MOT test number	369788137116
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2023-04-17 12:26
MOT test number	383066436986
Result	✓ Passed

MOT #10	2023-04-17 08:49
MOT test number	303330502940
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9	2022-04-06 09:45
MOT test number	417070351893
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both sides

**MOT #8** 2021-04-20 08:58**MOT test number** 392024927738**Result** ✓ Passed**MOT #7** 2021-04-14 14:36**MOT test number** 641788091163**Result** ✗ Failed**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #6** 2019-11-23 12:16**MOT test number** 362515316053**Result** ✓ Passed**Minor** Suspension arm ball joint dust cover severely deteriorated both front lower (5.3.4 (b) (i))**Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))**Advice** Brake pad(s) wearing thin front (1.1.13 (a) (ii))**MOT #5** 2018-11-29 12:00**MOT test number** 579565967296**Result** ✓ Passed**MOT #4** 2018-03-05 10:15**MOT test number** 384788503769**Result** ✓ Passed



MOT #3	2017-02-20 10:52
MOT test number	937701669390
Result	✓ Passed

MOT #2	2017-02-20 10:52
MOT test number	970025003824
Result	✗ Failed
Pass with rectification	Nearside Front Front position lamp(s) not working side (1.1.A.3b)
Pass with rectification	Offside Front Front position lamp(s) not working side (1.1.A.3b)

MOT #1	2016-03-10 12:17
MOT test number	577712297481
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Both rear tyres have age related cracks.
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Both front tyres worn on outer edges.
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
19 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	19 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-15
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2013-03-15	22 mi
Registration #2	2016-03-10	29.315 mi
Registration #3	2017-02-20	52.007 mi
Registration #4	2017-02-20	52.007 mi
Registration #5	2018-03-05	69.816 mi
Registration #6	2018-11-29	81.947 mi
Registration #7	2019-11-23	88.432 mi
Registration #8	2020-05-20	95.277 mi
Registration #9	2020-05-20	95.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2020-05-20	95.277 mi
Registration #12	2020-05-20	95.277 mi
Registration #13	2020-05-20	95.277 mi
Registration #14	2024-04-16	95.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	G4LACM940592
---------------	--------------