



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D5 SE LUX AWD
Colour	Grey
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-01-02
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-12
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	9

MOT #15	2023-09-13 15:05
MOT test number	992844421948
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Nail in tyre
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14**

2023-09-11 15:57

MOT test number

958626879165

Result

✗ Failed

Advice

Offside Rear Nail in tyre

Fail

Offside Front Brake hose excessively damaged (1.1.12 (b) (ii))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail

Rear Direction indicator incorrect colour Both rear indecator (4.4.3 (a))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Windscreen washer not working (3.5 (a))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #13

2022-09-07 13:20

MOT test number

145676485525

Result

✓ Passed

MOT #12

2021-10-12 14:38

MOT test number

233162245817

Result

✓ Passed

Minor

Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor

Offside Front Brake hose slightly twisted (1.1.12 (b) (i))

Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #11** 2020-10-13 15:26**MOT test number** 694430562423**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))**MOT #10** 2019-10-07 17:02**MOT test number** 826808161316**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Outer Edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-10-17 15:44**MOT test number** 367650103609**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #8** 2017-09-29 11:47**MOT test number** 764680496523**Result** ✓ Passed**MOT #7** 2016-09-05 10:34**MOT test number** 882257537621**Result** ✓ Passed**MOT #6** 2016-09-05 10:34**MOT test number** 795223401696**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #5** 2015-08-28 10:44**MOT test number** 514703215314**Result** ✓ Passed**MOT #4** 2014-08-29 10:23**MOT test number** 997161144255**Result** ✓ Passed**MOT #3** 2014-03-06 11:51**MOT test number** 648515764035**Result** ✓ Passed**MOT #2** 2014-03-05 13:11**MOT test number** 955924764049**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2013-02-28 13:24**MOT test number** 136909053031**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Outer sill covers fitted



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
12 September 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-02
Last registration	2023-09-13
Complete history	See info



Registration #1	2010-03-02	16 mi
Registration #2	2013-02-28	46.197 mi
Registration #3	2014-03-05	51.361 mi
Registration #4	2014-03-06	51.361 mi
Registration #5	2014-08-29	52.198 mi
Registration #6	2015-08-28	57.448 mi
Registration #7	2016-09-05	62.050 mi
Registration #8	2016-09-05	62.050 mi
Registration #9	2017-09-29	66.539 mi
Registration #10	2018-09-29	71.027 mi
Registration #11	2019-09-29	75.515 mi
Registration #12	2020-09-29	80.003 mi
Registration #13	2021-09-29	84.491 mi
Registration #14	2022-09-29	88.979 mi
Registration #15	2023-09-13	93.467 mi
Registration #16	2023-09-13	93.467 mi
Registration #17	2023-09-13	93.467 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1867 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	868290