





### General information

| Make                | PEUGEOT           |
|---------------------|-------------------|
| Model               | 206 SE            |
| Colour              | Silver            |
| Year of manufacture | 2004              |
| Top speed           | 99 mph            |
| 0 - 60 mph          | 15.2 seconds      |
| Gearbox             | 4 speed automatic |

### Engine & fuel consumption

| Power                   | 74 BHP              |
|-------------------------|---------------------|
| Max. torque             | 120 Nm at 3.400 rpm |
| Engine capacity         | 1.360 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 29.7 mpg            |
| Consumption extra urban | 52.3 mpg            |
| Consumption combined    | 40.9 mpg            |
| CO2 emission            | 165 g/km            |
| CO2 label               | G                   |







## Internet history

Entry 1

Date Pictures 2021-08-01

Listing price

View report

6



source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2025-03-22 |
|--------------------|------------|
| MOT pass rate      | 73 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 6          |
| Total advice items | 23         |
| Total items failed | 15         |

| MOT #22   | 2024-03-18 12:22 |
|---|------------------|
| <b>MOT test number</b> 69511344274  |                  |
| Result  | ✓ Passed         |
| Next expiry date  | 2025-03-22       |
| Advice Nearside Front Outer cv gaiter slight seepage of grease  |                  |
| Advice Oil leak, but not excessive (8.4.1 (a) (i))  |                  |
| Advice Front Brake disc worn, but not excessively nearside and offside (1.1.14 (a   | ) (i))           |
| <b>Advice</b> Rear Position lamp slightly affected by the operation of another lamp affected by operation of hazard lights nearside and offside (4.2.3 (c)) |                  |
| Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))  |                  |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))  |                  |

| MOT #21  |  | 2023-03-23 17:57 |
|----------|--|------------------|
| MOT test | number   | 906219852633     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Rear Inner Tyre worn close to legal limit/worn on edge 2.2mm (5.2.3 (e) | )                |
| Advice   | Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))                     |                  |





| MOT #20   | 2023-03-10 11:50        |
|---|-------------------------|
| MOT test number   | 711208729304            |
| Result  | 🗙 Failed                |
| FailNearside Front Upper Anti-roll bar linkage ball joint dust cover no longer preve(5.3.4 (b) (ii))                          | nts the ingress of dirt |
| Advice Front Exhaust has a minor leak of exhaust gases joint (6.1.2 (a))  |                         |
| Advice Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))   |                         |
| <b>Fail</b> Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, ingress of dirt (6.1.7 (g) (ii)) | no longer prevents the  |
| Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge 2.2mm (5.2   | 2.3 (e))                |
| FailOffside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevent(5.3.4 (b) (ii))                         | s the ingress of dirt   |
| <b>Fail</b> Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)                                  | )                       |

| MOT #19  |                                 | 2022-03-14 16:04 |
|----------|---------------------------------|------------------|
| MOT test | number                          | 946503528552     |
| Result   |                                 | ✓ Passed         |
| Advice   | Slight blow front exhaust joint |                  |
| Advice   | Engine damp with oil            |                  |
|          |                                 |                  |
| MOT #18  |                                 | 2022-03-14 14:43 |

|  | 2022-05-14 14.45             |
|--|------------------------------|
| MOT test number  | 697841495083                 |
| Result   | 🗙 Failed                     |
| <b>Fail</b> Nearside Front Outer Drive shaft joint constant velocity boot split or insec<br>ingress of dirt (6.1.7 (g) (ii)) | ure, no longer prevents the  |
| Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its   | s structure (5.2.3 (d) (ii)) |
| Advice Slight blow front exhaust joint   |                              |
| Advice Engine damp with oil  |                              |
|  |                              |





| MOT #17   | 2021-02-20 13:09   |
|---|--|
| MOT test number                                   | 118448928777   |
| Result  | ✓ Passed   |
|   |  |
| MOT #16   | 2021-02-20 13:09   |
| MOT test number                                   | 888104399479   |
| Result  | × Failed   |
| Pass with rectification                           | Nearside Front Position lamp not working (4.2.1 (a) (ii))                        |
| Pass with rectification                           | Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))   |
| Pass with rectification<br>lamps (4.7.1 (b) (ii)) | Nearside Registration plate lamp inoperative in the case of a single lamp or all |

| MOT #15         | 2019-06-01 11:00 |
|-----------------|------------------|
| MOT test number | 836677703010     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #14         | 2018-06-02 09:37 |
| MOT test number | 345539159035     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #13         | 2017-03-06 12:41 |
| MOT test number | 264419146021     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #12         | 2016-02-20 12:11 |
| MOT test number | 591885882486     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #11         | 2015-01-06 16:30 |

| MOT test number | 765816205093 |
|-----------------|--------------|
| Result          | ✓ Passed     |





| MOT #10                     | 2015-01-06 16:30  |
|-----------------------------|---|
| MOT test number             | 105856805440  |
| Result                      | × Failed  |
| Pass with rectification     | Exhaust system not adequately supported (7.1.1)                                 |
| Pass with rectification     | Nearside Front constant velocity joint gaiter insecure to the extent that it no |
| longer prevents the ingress | of dirt etc (2.5.C.1a)  |

| MOT #9   |   | 2014-02-18 17:01 |
|----------|---|------------------|
| MOT test | number  | 636889744030     |
| Result   |   | ✓ Passed         |
| Notice   | Advise both rear tyres on 2mm and wearing on edges. |                  |
| Notice   | Advise tracking.                                    |                  |
| Notice   | Advise both front tyres wearing on edges.           |                  |

| МОТ #8          | 2013-02-25 10:36 |
|-----------------|------------------|
| MOT test number | 727516553054     |
| Result          | ✓ Passed         |

| MOT #7  | 2013-02-23 16:59 |
|---|------------------|
| MOT test number   | 555324853000     |
| Result  | 🗙 Failed         |
| Fail Nearside Headlamp not working on dipped beam (1.7.5a)              |                  |
| Notice Oil leak   |                  |
| FailFront Brake pad(s) less than 1.5 mm thick (3.5.1g)                  |                  |
| Advice Nearside Outer Rear Tyre worn close to the legal limit (4.1.E.1) |                  |

| MOT #6          | 2011-08-25 16:19 |
|-----------------|------------------|
| MOT test number | 747797331264     |
| Result          | ✓ Passed         |





| MOT #5          | 2010-08-12 14:37 |
|-----------------|------------------|
| MOT test number | 391274020224     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #4          | 2009-08-25 15:03 |
| MOT test number | 234237739282     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #3          | 2009-08-24 17.40 |

| MOT #  | # <b>3</b> 2009-08-  | -24 17:40 |
|--------|--|-----------|
| MOT t  | test number 72342  | 26539218  |
| Result | lt   | 🗙 Failed  |
| Fail   | Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1       | .b)       |
| Fail   | Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) |           |

| MOT #2  | 2008-08-22 16:02 |
|---|------------------|
| MOT test number   | 391575638423     |
| Result  | 🗸 Passed         |
| <b>Notice</b> O/s an n/s/r tyres have flat spots from wheeles locking |                  |

| MOT #1   |  | 2007-08-09 11:02 |
|----------|--|------------------|
| MOT test | number   | 332951027402     |
| Result   |  | ✓ Passed         |
| Notice   | Both rear tyres have slight flat spots                             |                  |
| Advice   | Rear Exhaust has part of the system slightly deteriorated (7.1.1a) |                  |





Tax & MOT check

| ✓<br>Taxed              | ✓<br>МОТ                  |  |
|-------------------------|---------------------------|--|
| Tax due:<br>1 July 2024 | Expires:<br>22 March 2025 |  |
| Tax status              | Valid until 1 July        |  |
| Days left               | 63                        |  |
| MOT expiry date         | 22 March 2025             |  |
| Full MOT history        | See MOT history           |  |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |             |
|----------|-------------|
| Date     | FERM        |
| Category | <br>A PLANE |
| Туре     |             |
| Damage 2 | AMPLE       |
| Damage 2 | E Stand     |
| Date     | *           |
| Category | <br>ante.   |
| Туре     |             |

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 6.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 11 711 |





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and and a second s |             |
|--|-------------|
| **********   |             |
| *******  |             |
| ******   |             |
| *********  |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this PEUGEOT had different number plates.   |             |
| Number of plates   | ,           |
| Correct registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 23              |
| First mileage registration | 2004-08-19      |
| Last registration          | 2024-03-18      |
| Complete history           | <u>See info</u> |



| Registration #1  | 2004-08-19 | 29 mi      |
|------------------|------------|------------|
| Registration #2  | 2007-08-09 | 24.424 mi  |
| Registration #3  | 2008-08-22 | 37.337 mi  |
| Registration #4  | 2009-08-24 | 41.514 mi  |
| Registration #5  | 2009-08-25 | 41.514 mi  |
| Registration #6  | 2010-08-12 | 46.251 mi  |
| Registration #7  | 2011-08-25 | 52.328 mi  |
| Registration #8  | 2013-02-23 | 60.564 mi  |
| Registration #9  | 2013-02-25 | 60.570 mi  |
| Registration #10 | 2014-02-18 | 63.436 mi  |
| Registration #11 | 2015-01-06 | 64.963 mi  |
| Registration #12 | 2016-02-20 | 65.545 mi  |
| Registration #13 |            | 11.222 esi |
| Registration #14 |            | 11.117 est |
| Registration #15 |            | 11.227 esi |
| Registration #16 |            | 11.177 esi |
| Registration #17 |            | 11.222 esi |
| Registration #18 |            | 11.117 esi |
| Registration #19 |            | 11.777 esi |
| Registration #20 |            | 11.177 est |
| Registration #21 |            | 11.777 esi |
| Registration #22 |            | 11.177 est |
| Registration #23 |            |            |

More info >





## Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| 50482  |                  |
| S0501  |                  |
| \$0566 |                  |
| \$0567 |                  |
| S0569  |                  |

# Safety ratings

**NCAP** rating

Video

see crash video



| Dimensions & weight             |                       |
|---------------------------------|-----------------------|
| Width                           | 1652 mm               |
| Height                          | 1426 mm               |
| Length                          | 3835 mm               |
| Wheel base                      | 2445 mm               |
| Kerb weight                     | 1055 kg               |
| Additional information          |                       |
| Fuel tank capacity              | 50 I                  |
| Fuel delivery                   | Multi-Point Injection |
| Number of doors                 | 3                     |
| Number of axles                 | 2                     |
| Engine number<br>CarCheck.co.uk | FSM34685917           |