





report date: 2024-03-28

General information

Make	RENAULT
Model	LAGUNA DYNAMIQUE TOMTOM DCI FAP
Colour	White
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-01

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT #14	2021-07-05 12:32
---------	------------------

MOT test number 560268900725

Result ✓ Passed

Next expiry date 2022-07-04

MOT #13 2021-07-03 09:55

MOT test number 159500597452

Result X Failed

Fail Coil spring fractured or broken both front (5.3.1 (b) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #12 2020-06-11 12:11

MOT test number 399059395516

Result
✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2019-03-01 14:11

MOT test number 200546194177

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2019-02-28 16:04

MOT test number 213404391607

Result ★ Failed

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 3/11



Result

RO11CZW

report date: 2024-03-28

✓ Passed

MOT #9 2018-02-27 13:05

MOT test number 349757569478

Advice Nearside Rear Tyre low pressure

MOT #8 2017-01-24 12:59

MOT test number 141526222333

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2017-01-24 08:21

MOT test number 281312420896

Result X Failed

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #6 2016-02-23 15:09

MOT test number 911580206042

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Advice Both front tyres worn on inner edge

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT test number

Result

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Both front tyres worn on inner edge

Advice Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

MOT #4 2015-02-05 15:16 769926435029 **MOT** test number Result ✓ Passed **MOT** #3 2015-02-05 14:22 **MOT** test number 637766535055 Result × Failed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Front registration plate deteriorated (6.3.1d) Fail Nearside Headlamp not working on dipped beam (1.7.5a) Fail Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #2		2014-02-05 13:18
MOT test number		825806334058
Result		✓ Passed
MOT #1		2014-02-05 13:18
MOT test number		156116534099
Result		× Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

HEREERS .	

THE PROPERTY OF THE PROPERTY O	
Plate changes	More info >
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-24
Last registration	2021-07-05
Complete history	See info



Registration #1	2011-03-24	6 mi
Registration #2	2014-02-05	84.372 mi
Registration #3	2015-02-05	96.620 mi
Registration #4	2015-02-05	96.620 mi
Registration #5	2016-02-23	107.485 mi
Registration #6	2016-02-23	107.488 mi
Registration #7	2017-01-24	112.432 mi
Registration #8	2017-01-24	112.432 mi
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 10/11



RO11CZW report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2060 mm
Height	1445 mm
Length	4803 mm
Wheel base	2758 mm
Kerb weight	1492 kg
Max. allowed weight	2025 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Engine number Carcheck.co.uk	C016506	page 11/11