



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 R-DESIGN |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 100 BHP |
| Max. torque | 150 Nm at 4.000 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-10 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-19 |
| MOT pass rate | 75 % |
| MOT passed | 12 |
| Failed MOT tests | 4 |
| Total advice items | 46 |
| Total items failed | 16 |

| | |
|------------------|--|
| MOT #16 | 2023-09-20 06:50 |
| MOT test number | 863028479414 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-19 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #15 | 2022-09-08 09:20 |
| MOT test number | 730424342746 |
| Result | ✓ Passed |
| Advice | Offside Front Road wheel slightly distorted (5.2.2 (c) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #14**

2022-09-07 08:50

MOT test number

434272444035

Result

✗ Failed

Fail

Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2021-07-22 14:13

MOT test number

127695824907

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #122020-07-27 11:00

MOT test number997933614652

Result

✓ Passed

- Advice

Nearside Front Brake disc worn, but not excessively corroded (1.1.14 (a) (i))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement at rear (5.3.4 (a) (i))
- Advice

Power steering component has slight seepage from a component steering rack (2.1.5 (a))
- Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Offside Front Brake disc worn, but not excessively corroded (1.1.14 (a) (i))
- Advice

Offside headlamp slightly insecure
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement at rear (5.3.4 (a) (i))

**MOT #11**

2020-07-20 11:27

MOT test number

316397522141

Result**✗ Failed**

- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Power steering component has slight seepage from a component steering rack (2.1.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3-4-3mm (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside headlamp slightly insecure
- Advice** Offside Front Brake disc worn, but not excessively corroded (1.1.14 (a) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Brake disc significantly and obviously worn heavily corroded (1.1.14 (a) (i))
- Advice** Nearside Rear Nail in tyre punctured
- Fail** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement at rear (5.3.4 (a) (i))
- Fail** Nearside Rear All direction indicators incorrect colour (4.4.3 (a))
- Advice** Nearside Front Brake disc worn, but not excessively corroded (1.1.14 (a) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Rear Brake disc significantly and obviously worn heavily corroded (1.1.14 (a) (i))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement at rear (5.3.4 (a) (i))
- Minor** Nearside Front Outline marker lamp incorrect colour (4.2.3 (a) (i))

**MOT #10**

2019-03-19 12:51

MOT test number

763695899330

Result

✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9**

2018-03-14 13:42

MOT test number

319538225350

Result

✓ Passed

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Items removed from driver's view prior to test

**MOT #8** 2018-03-13 12:11**MOT test number** 330914270708**Result** ✗ Failed

- Advice** Items removed from driver's view prior to test
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2017-03-16 10:29**MOT test number** 693608519524**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear (2.4.G.2)
- Advice** Central Front Power steering pipe(s) or hose(s) slightly corroded (2.3.2)

MOT #6 2016-09-13 14:36**MOT test number** 627076163004**Result** ✓ Passed**MOT #5** 2016-03-16 13:36**MOT test number** 970915157590**Result** ✓ Passed



| | |
|-----------------|---------------------------|
| MOT #4 | 2015-03-14 10:50 |
| MOT test number | 268173075052 |
| Result | ✓ Passed |
| Notice | Light cracking rear tyres |

| | |
|-----------------|------------------|
| MOT #3 | 2014-03-17 13:39 |
| MOT test number | 798726374001 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #2 | 2014-03-13 15:56 |
| MOT test number | 455262374011 |
| Result | ✗ Failed |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #1 | 2013-10-04 09:28 |
| MOT test number | 479377273267 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
19 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 279 |
| MOT expiry date | 19 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YD60VTM |
| Plate since | 2019-09-28 |
| Current registration | YD60VTM |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2010-10-11 |
| Last registration | 2023-09-20 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-10-11 | 18 mi |
| Registration #2 | 2013-10-04 | 12.069 mi |
| Registration #3 | 2014-03-13 | 14.636 mi |
| Registration #4 | 2014-03-17 | 14.636 mi |
| Registration #5 | 2015-03-14 | 26.510 mi |
| Registration #6 | 2016-03-16 | 39.175 mi |
| Registration #7 | 2016-09-13 | 44.412 mi |
| Registration #8 | 2017-03-16 | 46.164 mi |
| Registration #9 | 2018-03-13 | 51.101 mi |
| Registration #10 | 2019-03-20 | 55.377 mi |
| Registration #11 | 2019-03-20 | 55.377 mi |
| Registration #12 | 2019-03-20 | 55.377 mi |
| Registration #13 | 2019-03-20 | 55.377 mi |
| Registration #14 | 2019-03-20 | 55.377 mi |
| Registration #15 | 2019-03-20 | 55.377 mi |
| Registration #16 | 2019-03-20 | 55.377 mi |
| Registration #17 | 2019-03-20 | 55.377 mi |
| Registration #18 | 2019-03-20 | 55.377 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4252 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1299 kg |
| Max. allowed weight | 1700 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|--------|
| Number of axles | 2 |
| Engine number | 181935 |