



CITROËN



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 EXCLUSIVE HDI
Colour	Silver
Year of manufacture	2003
Top speed	127 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	314 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-30
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2021-08-14
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #17 2020-08-15 09:29**MOT test number** 372742477560**Result** ✓ Passed**Next expiry date** 2021-08-14**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**MOT #16** 2019-08-13 14:44**MOT test number** 982448936944**Result** ✓ Passed**MOT #15** 2018-08-11 09:09**MOT test number** 321156424545**Result** ✓ Passed

**MOT #14** 2017-07-29 09:08**MOT test number** 296517620981**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2016-08-04 08:28**MOT test number** 787464755511**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**MOT #12** 2016-08-03 09:41**MOT test number** 374126664058**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Fail** Offside Rear Fluid suspension leaking (2.4.D.2)**Fail** Nearside Rear Fluid suspension leaking (2.4.D.2)**MOT #11** 2014-09-04 12:33**MOT test number** 486927744287**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres cracking

**MOT #10** 2013-09-04 12:39**MOT test number** 175007643230**Result** ✓ Passed**Notice** Nearside rear tyre worn to approx 2mm**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2012-09-12 12:56**MOT test number** 727746852235**Result** ✓ Passed**Notice** Nearside rear tyre worn to approx 2mm**MOT #8** 2012-09-05 12:05**MOT test number** 975619742271**Result** ✗ Failed**Notice** Nearside rear tyre worn to approx 2mm**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2011-09-12 11:15**MOT test number** 598765851266**Result** ✓ Passed**Notice** All tyres wearing to varying degrees, nearside rear worst**MOT #6** 2011-09-09 16:33**MOT test number** 686192151218**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** All tyres wearing to varying degrees, nearside rear worst

**MOT #5** 2010-09-06 12:29**MOT test number** 153789540208**Result** ✓ Passed**Notice** Rear tyres worn, nearside close to limit!**MOT #4** 2009-09-09 11:49**MOT test number** 843152559282**Result** ✓ Passed**Notice** All tyres wearing to various degrees**Notice** Slight judder nearside front brake**MOT #3** 2008-09-10 16:20**MOT test number** 752154158235**Result** ✓ Passed**Notice** Rear tyres getting low**MOT #2** 2007-09-05 11:47**MOT test number** 133478147293**Result** ✓ Passed**MOT #1** 2006-09-05 11:57**MOT test number** 644498246252**Result** ✓ Passed**Notice** Front tyres worn**Notice** Offside front strut damp



Tax & MOT check

X

Untaxed

Tax expired:
10 March 2021

X

MOT

Expired:
14 August 2021

Tax status	Expired at 10 March 2021
Days left	1146 days too late
MOT expiry date	14 August 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 VO53ENE
Plate since	2019-03-29
Current registration	 VO53ENE
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-09-12
Last registration	2020-08-15
Complete history	See info



Registration #1	2003-09-12	13 mi
Registration #2	2006-09-05	17.087 mi
Registration #3	2007-09-05	21.320 mi
Registration #4	2008-09-10	23.896 mi
Registration #5	2009-09-09	26.214 mi
Registration #6	2010-09-06	28.588 mi
Registration #7	2011-09-09	30.697 mi
Registration #8	2011-09-12	30.726 mi
Registration #9	2012-09-05	31.875 mi
Registration #10	2012-09-12	31.896 mi
Registration #11	2013-09-05	31.875 mi
Registration #12	2014-09-05	31.875 mi
Registration #13	2015-09-05	31.875 mi
Registration #14	2016-09-05	31.875 mi
Registration #15	2017-09-05	31.875 mi
Registration #16	2018-09-05	31.875 mi
Registration #17	2019-09-05	31.875 mi
Registration #18	2020-08-15	31.875 mi
Registration #19	2020-08-15	31.875 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2100 mm
Height	1476 mm
Length	4618 mm
Wheel base	2750 mm
Kerb weight	1485 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ174042937