



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Red
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-10
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-09-10
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	47
Total items failed	13

MOT #21 2021-09-11 12:53

MOT test number 260905179412

Result ✓ Passed

Next expiry date 2022-09-10

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Rear Brake hose slightly deteriorated both hoses (1.1.12 (b) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Front Anti-roll bar ball joint dust cover severely deteriorated both links both lower dust covers (5.3.4 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20 2021-04-09 09:27

MOT test number 164034700720

Result ✗ Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #19** 2019-10-11 10:40**MOT test number** 918880575559**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #18** 2018-10-02 14:06**MOT test number** 393540066967**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Tyre slightly damaged/cracking or perishing Both rear perished (5.2.3 (d) (ii))**MOT #17** 2018-10-02 09:34**MOT test number** 788459511271**Result** ✗ Failed**Advice** Tyre slightly damaged/cracking or perishing Both rear perished (5.2.3 (d) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16** 2017-10-03 14:09**MOT test number** 731711719476**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #15**

2017-10-03 11:12

MOT test number

695598839219

Result

✗ Failed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #14**

2016-10-15 10:20

MOT test number

775651709241

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #13**

2016-10-15 08:51

MOT test number

853197928983

Result

✗ Failed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Fuel pipe excessively damaged (7.2.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #12** 2015-10-17 08:02**MOT test number** 901220027690**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Surface corrosion starting on offside rear inner sill
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Centre exhaust deteriorating

MOT #11 2015-10-17 08:02**MOT test number** 787606937470**Result** ✗ Failed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Surface corrosion starting on offside rear inner sill
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Centre exhaust deteriorating
- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #10 2014-10-18 09:12**MOT test number** 539891394216**Result** ✓ Passed

- Notice** Both front wheel arch liners insecure
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #9** 2013-10-05 10:27**MOT test number** 629478773256**Result** ✓ Passed

- Notice** Engine undertray insecure/damaged
- Notice** Both sides front shock absorber dust covers split

MOT #8 2013-10-05 10:27**MOT test number** 216948973281**Result** ✗ Failed

- Notice** Engine undertray insecure/damaged
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Headlamp aim too high (1.8)
- Notice** Both sides front shock absorber dust covers split
- Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #7 2012-10-10 12:26**MOT test number** 225544382223**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nail in offside rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2011-10-18 10:27**MOT test number** 917761291265**Result** ✓ Passed



MOT #5	2010-10-05 08:54
---------------	------------------

MOT test number	843938070251
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-10-20 14:12
---------------	------------------

MOT test number	303443499454
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-08-29 09:11
---------------	------------------

MOT test number	952502248221
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-09-03 17:52
---------------	------------------

MOT test number	254756247242
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
---------------	--

MOT #1	2007-01-09 09:09
---------------	------------------

MOT test number	664149707079
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
9 September 2022

✕
MOT

Expired:
10 September 2022

Tax status	Expired at 9 September
Days left	598 days too late
MOT expiry date	10 September 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	LM53ZKZ
Plate since	2024-03-29
Current registration	LM53ZKZ
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-01-17
Last registration	2021-09-11
Complete history	See info



Registration #1	2004-01-17	13 mi
Registration #2	2007-01-09	18.552 mi
Registration #3	2007-09-03	21.475 mi
Registration #4	2008-08-29	24.111 mi
Registration #5	2009-10-20	28.111 mi
Registration #6	2010-10-05	31.792 mi
Registration #7	2011-10-18	35.935 mi
Registration #8	2012-10-10	43.677 mi
Registration #9	2013-10-05	49.934 mi
Registration #10	2014-10-18	55.382 mi
Registration #11	2015-10-17	61.028 mi
Registration #12	2016-10-17	66.675 mi
Registration #13	2017-10-17	72.322 mi
Registration #14	2018-10-17	77.969 mi
Registration #15	2019-10-17	83.616 mi
Registration #16	2020-10-17	89.263 mi
Registration #17	2021-09-11	94.910 mi
Registration #18	2021-09-11	94.910 mi
Registration #19	2021-09-11	94.910 mi
Registration #20	2021-09-11	94.910 mi
Registration #21	2021-09-11	94.910 mi
Registration #22	2021-09-11	94.910 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4ZZU499329