





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | TUCSON GDI SE NAV |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 113 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 132 Nm at 4.850 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.4 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 162 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date 2021-09-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

| Date | 2021-09-23 |
|------|------------|
| | |

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-09-23 | |
|---------------|--------------------|--|
| Pictures | 0 | |
| Listing price | <u>View report</u> | |

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-09-09 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 4 |

| MOT #5 | 2023-08-29 09:19 |
|---|------------------|
| MOT test number | 506923844229 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-09 |
| Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i)) | |

| MOT #4 | 2023-08-29 09:19 | |
|---|---|--|
| MOT test number | 566878692041 | |
| Result | ★ Failed | |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Pass with rectification (ii)) | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) | |
| Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i)) | | |

| MOT #3 | 2022-09-06 10:56 |
|-----------------|------------------|
| MOT test number | 248967651512 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

826577726365

Result

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expires: 9 September 2024

| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 216 |
| MOT expiry date | 9 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class 48 Band I First licence fee (12 months) £ 645,00,- Standard rate (12 months) £ 180,00,- Standard rate (6 months) £ 99,00,- Premium rate (12 months) £ 570,00,- Premium rate (6 months) £ 313,50,- | | |
|---|-------------------------------|------------|
| First licence fee (12 months) £ 645,00,- Standard rate (12 months) £ 180,00,- Standard rate (6 months) £ 99,00,- Premium rate (12 months) £ 570,00,- | Vehicle class | 48 |
| Standard rate (12 months) £ 180,00,- Standard rate (6 months) £ 99,00,- Premium rate (12 months) £ 570,00,- | Band | I |
| Standard rate (6 months) £ 99,00,- Premium rate (12 months) £ 570,00,- | First licence fee (12 months) | £ 645,00,- |
| Premium rate (12 months) £ 570,00,- | Standard rate (12 months) | £ 180,00,- |
| | Standard rate (6 months) | £ 99,00,- |
| Premium rate (6 months) £ 313,50,- | Premium rate (12 months) | £ 570,00,- |
| | Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
|--|-------------|
| | |
| THE STATE OF THE S | |
| *************************************** | |
| THE STATE OF THE S | |
| | |
| HEREER PARTY AND ADDRESS OF THE PARTY AND ADDR | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| | |
| Number of prates | |
| Current registration | NK SIX |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-09-10 |
| Last registration | 2023-08-29 |
| Complete history | See info |



| Registration #1 | 2018-09-10 | 7 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-09-07 | 16.077 mi |
| Registration #3 | 2021-09-07 | 16.077 mi |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 9.77 sc |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 66 |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 2065 mm |
|---------------------|---------|
| Height | 1650 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1414 kg |
| Max. allowed weight | 2030 kg |

Additional information

| Fuel tank capacity | 62 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |