



YR10VHJ

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Black
Year of manufacture	2010
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	39
Total items failed	8

MOT #15	2023-09-29 10:22
MOT test number	255486671673
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Oil leak, but not excessive from engine (8.4.1 (a) (i))

MOT #14	2022-10-05 07:56
MOT test number	204934467988
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Play in steering rack inner joint(s)
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2022-09-27 09:02

MOT test number

946226817638

Result**✗ Failed****Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice

Play in steering rack inner joint(s)

Fail

Exhaust system insecure (6.1.2 (a))

Advice

Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12

2021-08-18 10:15

MOT test number

205279082304

Result**✓ Passed****MOT #11**

2020-03-30 15:26

MOT test number

222900739970

Result**✓ Passed****Advice**

Coolant leak

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Play in steering rack inner joint(s)

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Nearside Play in steering rack inner joint(s)

**MOT #10**

2020-03-30 11:52

MOT test number

934293372037

Result**✗ Failed**

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coolant leak
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9

2019-04-03 12:45

MOT test number

703418450561

Result**✓ Passed**

- Advice** Coolant leak
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8**

2019-03-29 09:57

MOT test number

885992392551

Result**✗ Failed****Advice**

Coolant leak

Fail

Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

Fail

Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #7

2018-03-28 11:02

MOT test number

597697834684

Result**✓ Passed****Advice**

Nsr tyre worn 2.5m

Advice

Rear discs worn and corroded

Advice

Nsf tyre worn 2.5m

Advice

Osf tyre worn outer edge

**MOT #6**

2018-03-28 11:02

MOT test number

271730248332

Result

✗ Failed

Advice

Nsr tyre worn 2.5m

Advice

Rear discs worn and corroded

Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)

Advice

Nsf tyre worn 2.5m

Advice

Osf tyre worn outer edge

MOT #5

2017-03-13 16:38

MOT test number

527349090823

Result

✓ Passed

Advice

Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

Advice

Exhaust has a minor leak of exhaust gases flexi (7.1.2)

Advice

Exhaust heat shield insecure

MOT #4

2016-03-10 11:05

MOT test number

704026577992

Result

✓ Passed

MOT #3

2015-03-12 09:15

MOT test number

367251575036

Result

✓ Passed

MOT #2

2014-03-28 09:24

MOT test number

959297084061

Result

✓ Passed



MOT #1	2013-03-27 09:39
MOT test number	418496183091
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YR10VHJ
Plate since	2020-03-29
Current registration	 YR10VHJ
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-06
Last registration	2023-09-29
Complete history	See info



Registration #1	2010-04-06	26 mi
Registration #2	2013-03-27	40.452 mi
Registration #3	2014-03-28	56.618 mi
Registration #4	2015-03-12	70.512 mi
Registration #5	2016-03-10	83.306 mi
Registration #6	2017-03-13	91.761 mi
Registration #7	2018-03-28	104.114 mi
Registration #8	2018-03-28	104.114 mi
Registration #9	2019-03-29	114.759 mi
Registration #10	2019-03-29	114.759 mi
Registration #11	2019-03-29	114.759 mi
Registration #12	2019-03-29	114.759 mi
Registration #13	2019-03-29	114.759 mi
Registration #14	2019-03-29	114.759 mi
Registration #15	2019-03-29	114.759 mi
Registration #16	2019-03-29	114.759 mi
Registration #17	2019-03-29	114.759 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1070 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CGG 231658