



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-18
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #17</b>	2022-05-04 17:58
<b>MOT test number</b>	193603649423
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-05-03
<b>Minor</b>	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #16</b>	2021-05-04 13:32
<b>MOT test number</b>	554594548685
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Minor</b>	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Minor</b>	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #15**

2021-05-03 12:44

**MOT test number**

229427268745

**Result****✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #14**

2019-05-17 16:47

**MOT test number**

215376959124

**Result****✓ Passed**

- Minor** Nearside Rear Position lamp light intensity obviously reduced 1/2 bulbs not working (4.2.3 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Offside Rear Position lamp light intensity obviously reduced 1/2 bulbs not working (4.2.3 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #13**

2019-05-17 10:22

**MOT test number**

686220535487

**Result****✗ Failed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Items removed from driver's view prior to test
- Minor** Nearside Rear Position lamp light intensity obviously reduced 1/2 bulbs not working (4.2.3 (a) (i))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (h) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Offside Front Nail in tyre
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Offside Rear Position lamp light intensity obviously reduced 1/2 bulbs not working (4.2.3 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #12**

2018-05-12 09:03

**MOT test number**

272569841947

**Result****✓ Passed****MOT #11**

2018-05-12 09:03

**MOT test number**

527185026932

**Result****✗ Failed**

- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #10** 2018-02-28 10:05**MOT test number** 701311979442**Result** ✗ Failed**Advice** Nearside Rear tyre nail in tread**Fail** Brake pedal creeps down while the pedal is held under pressure (3.3.B.1a)**Fail** Nearside Headlamp aim too low (1.8)**MOT #9** 2017-02-18 16:22**MOT test number** 365812167551**Result** ✓ Passed**MOT #8** 2014-07-31 14:21**MOT test number** 105752414249**Result** ✓ Passed**MOT #7** 2014-07-31 12:03**MOT test number** 355732614233**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2012-12-02 15:16**MOT test number** 925757432376**Result** ✓ Passed**MOT #5** 2012-12-02 15:16**MOT test number** 477707332392**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)



MOT #4	2011-06-10 14:47
MOT test number	529161161196
Result	✓ Passed
MOT #3	2010-05-27 14:23
MOT test number	722007340117
Result	✓ Passed
MOT #2	2008-12-15 14:49
MOT test number	742320358389
Result	✓ Passed
MOT #1	2008-02-26 09:54
MOT test number	814627458041
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>HY05YXP</b>
Plate since	2024-03-28
Current registration	<b>HY05YXP</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-03-02
Last registration	2022-05-04
Complete history	<a href="#">See info</a>



Registration #1	2005-03-02	28 mi
Registration #2	2008-02-26	22.115 mi
Registration #3	2008-12-15	24.961 mi
Registration #4	2010-05-27	33.724 mi
Registration #5	2011-06-10	37.417 mi
Registration #6	2012-12-02	45.708 mi
Registration #7	2014-07-31	50.074 mi
Registration #8	2014-07-31	50.074 mi
Registration #9	2017-02-18	50.103 mi
Registration #10	2019-05-29	50.277 mi
Registration #11	2019-05-29	50.277 mi
Registration #12	2019-05-29	50.277 mi
Registration #13	2019-05-29	50.277 mi
Registration #14	2019-05-29	50.277 mi
Registration #15	2019-05-29	50.277 mi
Registration #16	2019-05-29	50.277 mi
Registration #17	2019-05-29	50.277 mi
Registration #18	2019-05-29	50.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	13030
---------------	-------