





report date: 2024-03-29

#### General information

Make	NISSAN
Model	MICRA IG-T ACENTA
Colour	White
Year of manufacture	2019
Top speed	109 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	51.4 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/11



### Internet history

#### Entry 1

Date 2022-04-21

Pictures 43

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-31
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	4

MOT #4		2024-01-29 16:07
MOT test	number	500310953172
Result		✓ Passed
Next expiry date 2025-01-3		2025-01-31
Advice Offside Rear Tyre slightly damaged/cracking or perishing And perishing (5.2.3 (d) (ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing And perishing (5.2.3 (d) (ii))		

MOT #3		2023-02-01 11:49
MOT test	number	740698618911
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



KL68DXC

report date: 2024-03-29

2023-01-31 17:15 **MOT #2 MOT test number** 864496483150 Result × Failed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #1	2	2022-01-25 11:01
MOT test	number	731065763475
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii)	)
Advice	Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when mistery	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



KL68DXC

report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-01-26
Last registration	2024-01-29
Complete history	See info



Registration #1	2019-01-26	16 mi
Registration #2	2022-01-25	8.370 mi
Registration #3		D.777 ea
Registration #4		71.777 66
Registration #5		D.777 66
Registration #6		11.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	79%
Pedestrian	79%
Safety systems	72%
Overall rating	82%
Video	see crash video



## Dimensions & weight

Width	1743 mm
Height	1455 mm
Length	3999 mm
Wheel base	2525 mm
Kerb weight	1065 kg
Max. allowed weight	1510 kg

# Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles2Engine numberD619240