



report date: 2022-08-09

General information

Make	MINI
Model	JOHN COOPER WORKS AUTO JOHN COOPER WORKS
Colour	Silver
Year of manufacture	2013
Top speed	147 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	208 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	39.8 mpg
CO2 emission	165 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-24
Pictures	34
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-09
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	6

MOT #10	2023-11-06 12:01
MOT test number	925089454972
Result	✓ Passed
Next expiry date	2024-11-09
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #9	2023-11-06 12:01
MOT test number	792464593308
Result	✗ Failed
Pass with rectification	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Pass with rectification	Nearside Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Pass with rectification	Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

MOT #8	2022-11-10 10:38
MOT test number	979823969866
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #7** 2022-11-10 10:38**MOT test number** 381728393460**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #6** 2021-10-21 12:18**MOT test number** 506475297340**Result** ✓ Passed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #5** 2020-10-03 10:12**MOT test number** 603553805278**Result** ✓ Passed**MOT #4** 2019-10-11 12:50**MOT test number** 945416508774**Result** ✓ Passed**MOT #3** 2018-10-17 12:45**MOT test number** 912397443686**Result** ✓ Passed**MOT #2** 2017-10-17 14:38**MOT test number** 229356730401**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2016-09-13 13:53
MOT test number	926243659606
Result	✓ Passed
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 November 2024

Tax status	Valid until 1 October
Days left	158
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-08-29
Current registration	 
Plate since	2019-08-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-21
Last registration	2023-11-06
Complete history	See info



Registration #1	2013-09-21	23 mi
Registration #2	2016-09-13	30.964 mi
Registration #3	2017-10-17	41.310 mi
Registration #4	2018-10-17	45.081 mi
Registration #5	2019-10-11	49.651 mi
Registration #6	2020-10-03	53.382 mi
Registration #7	2020-10-03	53.382 mi
Registration #8	2020-10-03	53.382 mi
Registration #9	2020-10-03	53.382 mi
Registration #10	2020-10-03	53.382 mi
Registration #11	2020-10-03	53.382 mi
Registration #12	2020-10-03	53.382 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3758 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A311J562