



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-09
Pictures	10
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #20	2022-06-16 12:24
MOT test number	855816841745
Result	✓ Passed
Next expiry date	2023-07-08
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2022-06-16 07:43
MOT test number	411534311520
Result	✗ Failed
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Central Rear fog lamp not working (4.5.1 (a) (ii))

MOT #18	2021-06-25 12:44
MOT test number	716563525570
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corroded in various places, from front of vehicle to rear wheel cylinders (1.1.11 (c))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge of tread, cracking and perishing (5.2.3 (e))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded in various places, from front of vehicle to rear wheel cylinders (1.1.11 (c))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing on edges of tread (5.2.3 (d) (ii))
Advice	Nearside Rear Shock absorbers has a slightly worn bush lower bush (5.3.2 (c))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2021-06-24 17:42

MOT test number

995546865797

Result**✗ Failed**

Advice Nearside Rear Brake pipe corroded, covered in grease or other material corroded in various places, from front of vehicle to rear wheel cylinders (1.1.11 (c))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge of tread, cracking and perishing (5.2.3 (e))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Rear Registration plate inscription illegible (0.1 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing on edges of tread (5.2.3 (d) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material corroded in various places, from front of vehicle to rear wheel cylinders (1.1.11 (c))

Advice Nearside Rear Shock absorbers has a slightly worn bush lower bush (5.3.2 (c))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #16

2020-07-09 14:23

MOT test number

636327262724

Result**✓ Passed**

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15

2019-05-13 15:52

MOT test number

303337067097

Result**✓ Passed**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-05-13 11:11**MOT test number** 645011617261**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2018-05-24 10:57**MOT test number** 979432787352**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #12** 2017-05-13 15:02**MOT test number** 325831721846**Result** ✓ Passed**MOT #11** 2017-05-13 12:12**MOT test number** 673494085529**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2016-05-10 13:15**MOT test number** 618175339135**Result** ✓ Passed**Advice** Both front tyres wearing on edges

**MOT #9** 2015-05-13 13:21**MOT test number** 977963735150**Result** ✓ Passed**MOT #8** 2014-03-11 14:54**MOT test number** 789920574030**Result** ✓ Passed**MOT #7** 2014-03-11 09:34**MOT test number** 115160874027**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Side repeater incorrect colour (1.4.A.2f)**Notice** Nail in nearside rear tyre**MOT #6** 2013-03-18 09:24**MOT test number** 685107573062**Result** ✓ Passed**Notice** Airbag warning light illuminated, recommend attention.**Notice** Rear exhaust silencer corroded.

**MOT #5** 2012-03-19 09:43**MOT test number** 876069772031**Result** ✓ Passed

- Notice** Nail in offside front tyre
- Notice** Nail in offside rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Air bag light is lit on dashboard
- Notice** Offside front tyre is cracking 175/65/14 82T 1476
- Notice** Nail in nearside rear tyre
- Notice** Exhaust is corroded
- Notice** Advised s and g check

MOT #4 2011-03-15 10:59**MOT test number** 898414471080**Result** ✓ Passed**MOT #3** 2010-03-16 10:29**MOT test number** 753865470092**Result** ✓ Passed**MOT #2** 2009-03-16 09:40**MOT test number** 411135979006**Result** ✓ Passed**MOT #1** 2008-03-17 11:50**MOT test number** 733767878042**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-03-21
Last registration	2022-06-16
Complete history	See info



Registration #1	2005-03-21	7 mi
Registration #2	2008-03-17	8.128 mi
Registration #3	2009-03-16	10.848 mi
Registration #4	2010-03-16	13.921 mi
Registration #5	2011-03-15	17.629 mi
Registration #6	2012-03-19	21.270 mi
Registration #7	2013-03-18	24.773 mi
Registration #8	2014-03-11	28.557 mi
Registration #9	2014-03-11	28.557 mi
Registration #10	2015-05-13	31.937 mi
Registration #11	2016-05-10	34.852 mi
Registration #12	2016-05-10	34.852 mi
Registration #13	2016-05-10	34.852 mi
Registration #14	2016-05-10	34.852 mi
Registration #15	2016-05-10	34.852 mi
Registration #16	2016-05-10	34.852 mi
Registration #17	2016-05-10	34.852 mi
Registration #18	2016-05-10	34.852 mi
Registration #19	2016-05-10	34.852 mi
Registration #20	2016-05-10	34.852 mi
Registration #21	2016-05-10	34.852 mi
Registration #22	2016-05-10	34.852 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FSR95191649