



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Yellow
Year of manufacture	2015
Top speed	104 mph
0 - 60 mph	13.5 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-05-10
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #10	2024-04-23 08:14
MOT test number	508839849639
Result	✓ Passed
Next expiry date	2025-05-10
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Engine undertray fitted not allowing for full inspection of engine bay area

MOT #9	2023-05-11 09:44
MOT test number	941240516974
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened nearside and offside rear (1.1.14 (a) (ii))
Advice	Engine undertray fitted not allowing for full inspection of engine bay area

MOT #8	2023-05-05 14:59
MOT test number	800883965753
Result	✗ Failed
Fail	Offside Front Service brake excessively binding (1.2.1 (f))
Advice	Brake disc worn, pitted or scored, but not seriously weakened nearside and offside rear (1.1.14 (a) (ii))
Advice	Engine undertray fitted not allowing for full inspection of engine bay area
Fail	Nearside Front Windscreen washer not working (3.5 (a))

**MOT #7** 2022-04-21 12:46**MOT test number** 494896843650**Result** ✓ Passed**Advice** Engine undertray fitted not allowing for full inspection of engine bay area**MOT #6** 2021-05-10 11:22**MOT test number** 534910589019**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #5** 2021-05-06 14:22**MOT test number** 104138460348**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))**Fail** Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))**Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))**MOT #4** 2020-04-11 11:14**MOT test number** 572395058008**Result** ✓ Passed**MOT #3** 2019-04-23 12:37**MOT test number** 233615573533**Result** ✓ Passed



MOT #2	2018-04-21 10:15
MOT test number	460370587147
Result	✓ Passed

  

MOT #1	2017-04-18 19:51
MOT test number	506099919381
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
10 May 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	10 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SM64SVY</b>
Plate since	2019-03-29
Current registration	 <b>SM64SVY</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-01-30
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2015-01-30	10 mi
Registration #2	2017-04-18	30.710 mi
Registration #3	2018-04-21	43.709 mi
Registration #4	2019-04-23	54.647 mi
Registration #5	2020-04-11	64.967 mi
Registration #6	2020-05-20	75.277 mi
Registration #7	2020-05-20	85.587 mi
Registration #8	2020-05-20	95.897 mi
Registration #9	2020-05-20	106.207 mi
Registration #10	2020-05-20	116.517 mi
Registration #11	2020-05-20	126.827 mi
Registration #12	2020-05-20	137.137 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2062 mm
Height	1856 mm
Length	4406 mm
Kerb weight	1496 kg
Max. allowed weight	2280 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2

Engine number

CAYDBG1624