





report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI X-LINE
Colour	Silver
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	10.7 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.1 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-29

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



KM05WRF report date: 2024-03-29

MOT history

MOT expiry date	2025-04-08	
MOT pass rate	76 %	
MOT passed	16	
Failed MOT tests	5	
Total advice items	15	
Total items failed	8	

MOT #21	2024-04-09 11:07
MOT test number	326354708334
Result	✓ Passed
Next expiry date	2025-04-08
Advice Front Brake disc worn, pitted or scored, but not seriously weaken	ned o/s and n/s (1.1.14 (a) (ii))

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))

Pass with rectification Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

MOT #19		2023-03-20 16:05
MOT test	number	230302017204
Result		✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor (4.7.1 (b)	Nearside Rear Registration plate lamp inoperative in the case of multiple lam (i))	ps or light sources

CarCheck.co.uk page 3/14



Advice

KM05WRF

report date: 2024-03-29

MOT #18	2023-03-20 14:16
MOT test number	834936485451
Result	× Failed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps of (4.7.1 (b) (i))	or light sources
Fail Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Nearside Front Windscreen wiper missing (3.4 (a))	

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #17	2021-08-24 08:18
MOT test number	664386085422
Result	✓ Passed
MOT #16	2020-08-21 08:14
MOT test number	452042722518
Result	✓ Passed
MOT #15	2019-05-22 10:07
MOT test number	393707679618
Result	✓ Passed
MOT #14	2018-05-29 11:49
MOT test number	439148030682
Result	✓ Passed

MOT #13	2017-05-23 08:45
MOT test number	945939889583
Result	✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2016-05-26 12:39

MOT test number 836166512983

MOT #11 2016-05-25 15:12

MOT test number 275579323643

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Electronic stability system warning lamp indicates a fault (3.4.1c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10 2015-05-14 09:30

MOT test number 198254635124

MOT #9 2014-05-16 11:22

MOT test number 885896534167

Result

Passed

Advice Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

Notice Front windscreen cracked.

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Notice Front windscreen cracked.

MOT #7	2013-05-08 11:48
MOT test number	107928023181
Result	✓ Passed
Notice Nail in nearside rear tyre	

MOT #6	2012-05-16 11:22
MOT test number	609187932100
Result	✓ Passed
MOT #5	2011-05-18 10:03
MOT test number	248788231407

Result	✓ Passed
MOT #4	2010-05-24 10:22

MOT test number 191434640165

Result ✓ Passed

MOT #3	2009-05-19 14:12
MOT test number	980039239188
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

 MOT #2
 2008-03-25 11:30

 MOT test number
 741975088016

 Result
 ✓ Passed

 MOT #1
 2008-03-25 11:30

 MOT test number
 231405288061

 Result
 X Failed

 Pass with rectification

 Offside Front Headlamp aim too high (1.8)

CarCheck.co.uk page 7/14





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner	history

Sime misery	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	

THE STREET STREE	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-06-06
Last registration	2024-04-09
Complete history	See info



Registration #1	2005-06-06	8 mi
Registration #2	2008-03-25	8.357 mi
Registration #3	2009-05-19	9.808 mi
Registration #4	2010-05-24	11.800 mi
Registration #5	2011-05-18	13.713 mi
Registration #6	2012-05-16	16.452 mi
Registration #7	2013-05-08	17.581 mi
Registration #8	2014-05-13	19.779 mi
Registration #9	2014-05-16	19.779 mi
Registration #10	2015-05-14	20.906 mi
Registration #11	2016-05-25	21.491 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		0.074
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 66

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4676 mm
Wheel base	2725 mm
Kerb weight	1604 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	66 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 14/14

Engine number

DYTL4007444