





report date: 2024-03-29

#### General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	White
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

# MOT history

MOT expiry date	2024-07-27
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #10		2023-07-26 13:03
MOT test	number	148267213152
Result		✓ Passed
Next expi	ry date	2024-07-27
Advice	Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Underbody corroded	

MOT #9		2023-07-26 13:03
MOT test	number	190778947684
Result		<b>★</b> Failed
Advice	Rear Brake hose has slight corrosion	n to ferrule (1.1.12 (f) (i))
Advice	Advice Underbody corroded	
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Pass wit	h rectification Driver's view of th	e road through the swept area of the windscreen significantly
affected by	an obstruction (3.1 (a) (ii))	
Advice	Suspension component corroded bu	t not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #8		2022-07-05 10:54
MOT test	number	709385380243
Result		✓ Passed
Advice	Brake hose has slight corrosion to ferrule Front & rear (1.1.12 (f) (i))	
Advice	Rear Axle corroded	
Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))		
Advice	Front Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))	
Advice	Front Suspension arm corroded but not seriously weakened Both front (5.3.	.3 (b) (i))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Rear Inner Sill corroded	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both fr	ont (1.1.14 (a) (ii))
Advice	Front Tyre slightly damaged/cracking or perishing Both front (5.2.3 (d) (ii))	

MOT #7	2021-07-28 16:24
MOT test number	394694335457
Result	✓ Passed
MOT #6	2020-02-17 14:50
MOT test number	724378171170
Result	✓ Passed

MOT #5		2020-02-17 10:44
MOT test	number	916216231689
Result		<b>×</b> Failed
MAJOR	Offside Brake pipe excessively corroded front to rear (1.1.11 (c))	
MAJOR	Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4	2019-02-08 14:38
MOT test number	938087172063
Result	<b>✓</b> Passed
MOT #3	2018-02-08 11:08
MOT test number	655475393946
Result	✓ Passed
MOT #2	2017-02-07 10:59
MOT test number	384982336804
Result	✓ Passed
MOT #1	2016-02-10 10:02
MOT test number	241690513975
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check

Tax expired: 25 April 2024





Tax status	Expired at 25 April 2024
Days left	5 days too late
MOT expiry date	27 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
-------	---------

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		
MARKET STATE OF THE STATE OF TH		
***************************************		
	More info >	
Plate changes		
See in this check if this SUZUKI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-01-31
Last registration	2023-07-26
Complete history	See info



Registration #1	2013-01-31	20 mi
Registration #2	2016-02-10	44.010 mi
Registration #3	2017-02-07	53.929 mi
Registration #4	2018-02-08	66.494 mi
Registration #5	2019-02-08	82.950 mi
Registration #6	2020-02-17	97.380 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.777 es

More info >

CarCheck.co.uk page 10/11



YB62XOV report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

## Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1720082

CarCheck.co.uk page 11/11