




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 2


Date	2024-04-24
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-03-27
Pictures	4
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-01-05
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	14
Total items failed	16

MOT #13	2024-04-26 10:20
MOT test number	657000298638
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2024-02-06 17:03
MOT test number	836001413343
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Front Tyre slightly damaged/cracking or perishing both front tyres (5.2.3 (d) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11**

2023-01-06 11:05

MOT test number

630899694039

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing CRACKED ON OUTER TREAD (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing CRACKED ON OUTER WALL.... (5.2.3 (d) (ii))

Advice Offside Front TYRE WORN ON OUTER TREAD...

MOT #10

2023-01-06 09:32

MOT test number

466072696729

Result

✗ Failed

Fail Nearside Front Headlamp aim too high (4.1.2 (a))

Fail Front Windscreen wiper does not clear the windscreen effectively BOTH FRONT WIPER BLADES TORN.... (3.4 (b) (ii))

Advice Offside Front TYRE WORN ON OUTER TREAD...

Advice Nearside Rear Tyre slightly damaged/cracking or perishing CRACKED ON OUTER WALL.... (5.2.3 (d) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Headlamp aim too high (4.1.2 (a))

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing CRACKED ON OUTER TREAD (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #9** 2021-12-17 09:11**MOT test number** 171573917979**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Drivers outer door handle partly broken but still functioning**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #8** 2020-10-03 08:43**MOT test number** 589417142357**Result** ✓ Passed**MOT #7** 2019-10-11 14:12**MOT test number** 449898329990**Result** ✓ Passed**MOT #6** 2018-09-24 15:38**MOT test number** 222611576596**Result** ✓ Passed**MOT #5** 2018-09-24 13:15**MOT test number** 662744998203**Result** ✗ Failed**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2017-10-12 13:17**MOT test number** 410810804826**Result** ✓ Passed



MOT #3	2017-01-10 16:41
MOT test number	747636953288
Result	✓ Passed

MOT #2	2017-01-10 16:41
MOT test number	345170502162
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Nearside Stop lamp not working (1.2.1b)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)

MOT #1	2016-01-13 09:37
MOT test number	987067372117
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
5 January 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	5 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LO62UMG
Plate since	2019-06-29
Current registration	 LO62UMG
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-02-18
Last registration	2024-04-26
Complete history	See info



Registration #1	2013-02-18	11 mi
Registration #2	2016-01-13	21.764 mi
Registration #3	2017-01-10	22.401 mi
Registration #4	2017-01-10	22.401 mi
Registration #5	2017-10-12	22.409 mi
Registration #6	2018-09-24	29.624 mi
Registration #7	2018-09-24	29.625 mi
Registration #8	2019-10-11	35.388 mi
Registration #9	2020-05-20	35.397 mi
Registration #10	2020-05-20	35.397 mi
Registration #11	2020-05-20	35.397 mi
Registration #12	2020-05-20	35.397 mi
Registration #13	2020-05-20	35.397 mi
Registration #14	2020-05-20	35.397 mi
Registration #15	2020-05-20	35.397 mi
Registration #16	2020-05-20	35.397 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K