



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 S D V50
Colour	Black
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

## Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-09-29
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-03-16
Pictures	25
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-03-12
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	37
Total items failed	2

MOT #20	2024-03-13 16:45
MOT test number	268157210042
Result	✓ Passed
Next expiry date	2025-03-12
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Rear brake discs worn
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Exhasut rear box deteriorated

MOT #19	2024-03-08 09:04
MOT test number	382387264643
Result	✗ Failed
MAJOR	Rear Sub-frame damaged and seriously weakened (5.3.3 (b) (i))
Advice	Rear brake discs worn
MAJOR	Nearside Front Service brake excessively binding (1.2.1 (f))
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Exhasut rear box deteriorated
DANGEROUS	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure Inner side wall (5.2.3 (d) (ii))
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #18** 2024-02-19 17:04**MOT test number** 343849020618**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Badly scrubbed inner edge (5.2.3 (e))**Advice** Rear brake discs worn**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Badly worn (5.3.4 (a) (i))**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**MAJOR** Front Service brake excessively fluctuating (1.2.1 (e))**DANGEROUS** Offside Front Road wheel fractured Inner rim (5.2.2 (a))**Advice** Front brakes worn**MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases Rear box deteriorated (6.1.2 (a))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**MOT #17** 2023-05-04 16:22**MOT test number** 724090220440**Result** ✓ Passed**MOT #16** 2023-04-22 12:29**MOT test number** 923222717654**Result** ✗ Failed**MAJOR** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2022-06-13 11:12**MOT test number** 271905208754**Result** ✓ Passed**MOT #14** 2021-10-14 09:43**MOT test number** 188878034276**Result** ✓ Passed**MOT #13** 2020-10-28 13:57**MOT test number** 172349331625**Result** ✓ Passed**MOT #12** 2020-10-27 13:22**MOT test number** 790396185851**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge wear too inner edges (5.2.3 (e))**Advice** Front Tyre worn close to legal limit/worn on edge Both Tyres wear too inner edges (5.2.3 (e))**MOT #11** 2019-12-20 14:52**MOT test number** 207190871214**Result** ✓ Passed**MOT #10** 2019-12-20 14:52**MOT test number** 919626536362**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #9** 2019-01-18 16:03**MOT test number** 836000663066**Result** ✓ Passed**MOT #8** 2019-01-11 16:18**MOT test number** 774692941403**Result** ✗ Failed

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm INNER EDGE WORN OUT (5.2.3 (e))

**MOT #7** 2018-01-11 10:45**MOT test number** 135692377212**Result** ✓ Passed**MOT #6** 2018-01-11 10:45**MOT test number** 747347443047**Result** ✗ Failed

**Pass with rectification** Fuel system component leaking (7.2.3)

**MOT #5** 2017-01-13 17:00**MOT test number** 934240649889**Result** ✓ Passed**MOT #4** 2016-01-18 09:49**MOT test number** 576456654624**Result** ✓ Passed

**Advice** Engine covers / undertrays fitted

**Advice** Rear tyre going out of shape

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Residue of brake fluid on reservoir



<b>MOT #3</b>	2014-12-02 16:46
---------------	------------------

<b>MOT test number</b>	197586734354
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

<b>MOT #2</b>	2013-11-29 16:36
---------------	------------------

<b>MOT test number</b>	257393033339
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-11-30 12:37
---------------	------------------

<b>MOT test number</b>	445875732395
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
12 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	12 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>YY59LKF</b>
Plate since	2019-03-29
Current registration	<b>YY59LKF</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-12-08
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2009-12-08	11 mi
Registration #2	2012-11-30	32.575 mi
Registration #3	2013-11-29	43.026 mi
Registration #4	2014-12-02	51.188 mi
Registration #5	2016-01-18	60.586 mi
Registration #6	2017-01-13	63.346 mi
Registration #7	2018-01-11	72.841 mi
Registration #8	2018-01-11	72.841 mi
Registration #9	2019-01-11	79.204 mi
Registration #10	2019-01-18	79.389 mi
Registration #11	2019-12-20	92.458 mi
Registration #12	2019-12-20	92.458 mi
Registration #13	2020-01-20	92.458 mi
Registration #14	2020-01-20	92.458 mi
Registration #15	2020-01-20	92.458 mi
Registration #16	2020-01-20	92.458 mi
Registration #17	2020-01-20	92.458 mi
Registration #18	2020-01-20	92.458 mi
Registration #19	2020-01-20	92.458 mi
Registration #20	2020-01-20	92.458 mi
Registration #21	2020-01-20	92.458 mi
Registration #22	2020-01-20	92.458 mi
Registration #23	2020-01-20	92.458 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1519 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	565929
---------------	--------