



VN58YWG

report date: 2024-03-28

General information

| | |
|---------------------|---------------------|
| Make | FIAT |
| Model | GRANDE PUNTO ACTIVE |
| Colour | White |
| Year of manufacture | - |
| Top speed | 96 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 64 BHP |
| Max. torque | 102 Nm at 3.000 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 46.3 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-28 |
| Pictures | 20 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history****MOT #20**

2023-09-20 09:22

MOT test number

812906893356

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Engine mounting damaged or deteriorated resulting in excessive movement lower gearbox mounting (6.1.8 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))
- Advice** Advise nearside rear lower outer body sill damaged.
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #19**

2022-09-26 10:22

MOT test number

975183401132

Result

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Central Front Gearbox mounting defective
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2022-09-23 12:41

MOT test number

184846173729

Result

✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Central Front Gearbox mounting defective
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2021-09-27 14:56

MOT test number

594081673823

Result

✓ Passed

- Advice** Coolant level low
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

MOT #16

2021-09-24 09:26

MOT test number

396709434971

Result

✗ Failed

- Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp indicator inop sidelights flash (4.2.3 (c))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Coolant level low
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))

**MOT #15** 2020-09-22 08:28**MOT test number** 479988974403**Result** ✓ Passed**Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2020-09-22 08:28**MOT test number** 715026060085**Result** ✗ Failed**Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #13** 2019-09-05 13:17**MOT test number** 424983125505**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2019-09-05 08:45

MOT test number

480434212093

Result**✗ Failed****Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Fail** Nearside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Pass with rectification** Offside Rear Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MOT #11**

2018-08-03 13:53

MOT test number

377949924725

Result**✓ Passed****Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**Advice** Rear exhaust box corroded**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2017-08-10 14:52

MOT test number

168155665630

Result

✓ Passed

- Advice** Offside Front Wearing on inner edge of tread
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Exhaust system corroded
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Outer Door handle has poor operation
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9

2017-08-10 11:33

MOT test number

661782259859

Result

✗ Failed

- Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Exhaust system corroded
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Front Wearing on inner edge of tread

**MOT #8**

2016-08-19 14:40

MOT test number

439844713418

Result

✓ Passed

- Advice** Slight oil leaking from nearside gearbox diff seal
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit low on edge (4.1.E.1)
- Advice** Rear exhaust corroded and in poor condition
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #7

2016-08-18 14:01

MOT test number

969068935094

Result

✗ Failed

- Advice** Slight oil leaking from nearside gearbox diff seal
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Rear exhaust corroded and in poor condition
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit low on edge (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

**MOT #6**

2016-08-05 16:00

MOT test number

705045744806

Result**✗ Failed**

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Rear exhaust box rusting
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Coil spring not correctly located (2.4.C.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Child seat fitted to o/side rear

MOT #5

2015-07-02 10:20

MOT test number

788423785161

Result**✓ Passed**

- Notice** Advise rear silencer deteriorated

MOT #4

2015-07-01 13:05

MOT test number

859432985166

Result**✗ Failed**

- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Notice** Advise rear silencer deteriorated



| | |
|-----------------|---|
| MOT #3 | 2014-07-28 09:07 |
| MOT test number | 899639104223 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #2 | 2012-08-10 11:18 |
| MOT test number | 839193022245 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2011-08-05 14:39 |
| MOT test number | 105707211226 |
| Result | ✓ Passed |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2008-12-30 |
| Last registration | 2023-09-20 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-12-30 | 26 mi |
| Registration #2 | 2011-08-05 | 21.860 mi |
| Registration #3 | 2012-08-10 | 26.761 mi |
| Registration #4 | 2014-07-28 | 46.265 mi |
| Registration #5 | 2015-07-01 | 56.823 mi |
| Registration #6 | 2015-07-02 | 56.823 mi |
| Registration #7 | 2016-08-05 | 66.740 mi |
| Registration #8 | 2016-08-18 | 66.763 mi |
| Registration #9 | 2016-08-19 | 66.765 mi |
| Registration #10 | 2017-08-10 | 75.674 mi |
| Registration #11 | 2017-08-10 | 75.698 mi |
| Registration #12 | 2017-08-10 | 75.698 mi |
| Registration #13 | 2017-08-10 | 75.698 mi |
| Registration #14 | 2017-08-10 | 75.698 mi |
| Registration #15 | 2017-08-10 | 75.698 mi |
| Registration #16 | 2017-08-10 | 75.698 mi |
| Registration #17 | 2017-08-10 | 75.698 mi |
| Registration #18 | 2017-08-10 | 75.698 mi |
| Registration #19 | 2017-08-10 | 75.698 mi |
| Registration #20 | 2017-08-10 | 75.698 mi |
| Registration #21 | 2017-08-10 | 75.698 mi |
| Registration #22 | 2017-08-10 | 75.698 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1687 mm |
| Height | 1490 mm |
| Length | 4030 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1040 kg |
| Max. allowed weight | 1590 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 4625351 |