





report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI
Colour	Black
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	26.9 mpg
CO2 emission	278 g/km
CO2 label	М



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-08-18

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



KW57NPE report date: 2024-03-28

MOT history

MOT expiry date	2024-06-19
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	21
Total items failed	11

MOT #17	2023-06-07 10:30
MOT test number	430603372123
Result	✓ Passed
Next expiry date	2024-06-19
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16			2023-06-07 10:30
MOT test nu	mber		424440019321
Result			<b>X</b> Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))			
<b>Pass with r</b> (4.1.2 (c))	rectification	Nearside Front Headlamp aim projected beam imag	ge is obviously incorrect

MOT #15	2022-06-20 10:33
MOT test number	808863791345
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

455407911075

Result

Minor
(b) (i))

Advice
Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

Minor
Nearside Front Outer Brake hose slightly deteriorated (1.1.12 (b) (ii))

Minor
Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice
Offside Front Outer Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #13** 2021-06-14 09:51 **MOT** test number 731472019035 Result × Failed Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Front Outer Brake hose slightly deteriorated (1.1.12 (b) (ii)) Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i)) Pass with rectification Central Rear Seat belt retracting mechanism defective (7.1.2 (e)) **Advice** Offside Front Outer Brake hose slightly deteriorated (1.1.12 (b) (ii)) Pass with rectification Windscreen washer not working (3.5 (a))

MOT #12	2020-02-07 16:42
MOT test number	917219332429
Result	✓ Passed
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #11** 2020-02-07 09:35

MOT test number 641928120012

**Result** X Failed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Central Rear Seat belt not functioning as intended centre seat belt not pulling out (7.1.2 (c))

**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10 2019-02-08 15:46

MOT test number 482189279646

Advice Nearside Front Upper Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #9 2019-02-08 13:11

**MOT test number** 629337793175

**Result** X Failed

Fail Central Rear Seat belt retracting mechanism defective (7.1.2 (e))

Advice Nearside Front Upper Suspension component ball joint has slight play (5.3.4 (a) (i))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Fail** Nearside Front Position lamp not working (4.2.1 (a))

MOT #8 2018-02-12 15:45

**MOT test number** 428704130322

Advice Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #7 2017-02-02 10:45

**MOT test number** 912188543111

**Result** ✓ Passed

MOT #6 2016-01-22 16:37

**MOT test number** 108112711091

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-08-13 11:37

**MOT test number** 246805724277

Notice N/s/r tyre close to legal limit

MOT #4 2014-08-13 11:17

MOT test number 505295924287

Result X Failed

**Notice** N/s/r tyre close to legal limit

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Registration plate lamp not working (1.1.C.1d)

MOT #3 2013-03-18 14:10

**MOT test number** 609157473073

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #2		2012-07-04 15:09
MOT test	number	209136282432
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2011-03-04 14:34
MOT test number	207093261033
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	19 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damago 2	

Damage 2

Date
Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



KW57NPE report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	
*********	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-02-20
Last registration	2023-06-07
Complete history	See info



Registration #1	2008-02-20	7 mi
Registration #2	2011-03-04	42.508 mi
Registration #3	2012-07-04	54.710 mi
Registration #4	2013-03-18	60.603 mi
Registration #5	2014-08-13	69.083 mi
Registration #6	2014-08-13	69.083 mi
Registration #7	2016-01-22	80.258 mi
Registration #8	2017-02-02	86.925 mi
Registration #9	2018-02-12	94.326 mi
Registration #10	2019-02-08	101.970 mi
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		91,700 esi
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Max. allowed weight	2945 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

CarCheck.co.uk page 14/14

Number of axles	2

BKS 081949

**Engine number**